



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

Date of thorough examination : 21-06-2026		Date of issue : 21-06-2026		Report No. : ESICO-LFT-R26-9393	
Name & Address of employer		Location		Sticker	
SUDHIR EQUIPMENT RENTALS		AL HASSA 7 SITE		11045	
Standards SASO GSO EN 280 & ANSI A92.6					
Equipment Identification No	Equipment Description		Safe Working Load(s)	Date of Manufacture	Manufacturer Name
SD16ESL-1793 OR JPAC124J01215	SCISSORLIFT MODEL: S1614AC Overall Length: 2.84 m Platform Size (L x W): 2.64 m x 1.12 m Max. Working Height: 15.70 m		363 KG	U/N	DINGLI
Is this the first examination after installaton or assembly at a new site or location? Yes ☐ - ☐ No ☒			Was the examination carried out within an interval of? - 12 Months		
If the answer to the above question is YES, has the equipment been installed correctly? Yes ☐ - ☐ No ☐			In accordance with an examination scheme? Yes ☒ No ☐ - ☐		
			After the occurence of exceptional circumstances? Yes ☐ - ☐ No ☒		
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE					
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?					No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)				Yes by : NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE					
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE					
Observation/additional comments relative to this thorough examination : NO DEFECT FOUND AT THE TIME OF INSPECTION.					



For confirmation scan QR code
search with report number : **ESICO-LFT-R26-9393**



☒ Safe to operate

Next Inspection : 20-06-2027

Inspected by : ANSON

