مؤسسة جبال هيما لايا للفحص

JABAL HEMALAYA FOR INSPECTIONS

Rejection Report of Thorough Examination of Generator

Report No: JHI-9775-26-R1 **Date of Inspection: 08-08-2026**

Name of the owner company:	Location:
SUDHIR EQUIPMENT RENTAL COMPANY	JEDDAH-KSA

Equipment Details: DIESEL ENGINE GENERATOR

Reference Regulations:	Maker & Date of Manufacture:
SASO-GSO-ISO-8528-13,SASO-IEC-60034-22,BS EN ISO 8528-13,BS ISO 16110-1	VARADA & 2022

Sticker No.	Owner ID.	Model No.	Serial No./ Chassis No.
NA	SG-834-48	VEPL-160-CDP	VEPL/2023-24/097
Rated voltage.	**Frequency.**	**Rpm.**	**Phase.**
400V	60Hz	1800	3

Description of Test: Based on Thorough Visual Examination, the equipment was found Unsatisfactory.

Date of Last Examination	Date of Next Examination
NA	COMPLETE DAMAGED CANNOT USE

RECOMMENDATION / REMARKS

The equipment was inspected, it was found to contain deviations from the standard requirements.
The final observation is given in the annex.

After the inspection and testing of the equipment described in this report, the equipment found to contain defects likely to affect safety. Due to the highlighted items in the subsequent pages (Remarks/Recommendation Section), the equipment is not safe for intended use. Re-inspection will be required after rectification.

Authorized Name: **M.MOHAMED AZARUDEEN** Surveyor's Name: **KHAIF**

Authorized Signature: M. Mohamed Azarudeen Surveyor's Signature:

This Rejection is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Jabal Hemalaya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hemalaya For Inspections nor their Engineer be liable for any injury or damage to any person or occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hemalaya For Inspections and which are covered only by this certificate. Any person not a party to the contract pursuant to which this document is delivered may not assert claim against Jabal Hemalaya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may provide. This certificate shall not be reproduced except in full without the approval of Jabal Hemalaya For Inspections.
Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damage/losses associated to the equipment/material

Annex to Rejection Report of Thorough Examination

Report No.: JHI-9775-26-R1 **Date of Inspection:** 08-08-2026

Comments:

- Diesel generator found extensively fire-damaged, with several areas showing evidence of burning.
- Major fire damage observed to the engine, electrical components, wiring, and associated systems.
- Generator is not considered safe for operation in its present condition.
- Visual and functional inspection was not satisfactory due to the extent of fire damage.
- it cannot be repaired because of total loss
- All damaged components, wiring, electrical systems, and safety devices .

The equipment is **not fit for operation** and is **rejected**

Surveyor's Name: KHAIF **Surveyor's Signature:**

INSPECTIONS

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh. Po. 12628
CR No: 1010927177, Tel: 0112334900, Email: info@jhinspection.com, www.jhinspection.com