شـــركة تـــوف ســـــود لهندسة السلامة
TÜV SÜD for Safety Engineering
Tel:013 361 2121 - 013 833 2229 Email: info.ju@tuvsud.com

LIFTING EQUIPMENT INSPECTION REPORT	RPO No. NA	Org. Code		CRM No. NA	Report No: TS-YA-26-13619	
	Area :	Inspection Date:		Inspection Time:	Previous sticker	Issued by
	Yanbu	29/Sep/2026		11:00 AM	6495	B.V
Department/Contractor	Equipment No	Equipment Location:		Inspection Result :	New sticker No.	
Sudhir Equipment Rental Company	SRC-STC-050-090	Nesma Yard		Pass	TUV-SUD-15804	
Manufacturer:	Model:	Capacity:	Type:	Equipment Serial Number	Sticker Expiration Date:	
SANY 2026	STC 500 C5	50 tonne	Truck Mounted Crane	TC2050CG0306	28/Dec/2026	

Above equipment was inspected by **TÜV SÜD for Safety Engineering** accordance with applicable Saudi Aramco GI's, ASME and API standards. Deficiencies that require corrective action listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

NO.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	Periodic inspection and functional test for Mobile Crane (Truck Mounted Crane) as per ASME B30.5 & G.I. 7.30:	
	Found satisfactory at the time of inspection	
01	Chassis No.: LFCNMF5P8T2000762	
02	Plate No.: 1947 HAA	
03	Boom: 11.3 m to 41.0 m	
04	Main hook: SWL 50 tonne, 4 fall, 16 mm wire rope diameter, Weight 400 kg, S/N HCZ2550639	
05	Aux. hook: 5 ton, Weight 85 kg , S.N ZX26012938	
06	Fly jib: stowed	

RECEIVER NAME	Shree		TECHNICAL REVIEWER NAME:	Mohamad Moaen Deeb	INSPECTOR NAME	Yousry Ali
BADGE No	CAC018311		Received Date:	29/09/2026	SAP NUMBER	80019211
TELEPHONE No	0551664638		Reviewed Date:	29/09/2026	SIGNATURE	
SIGNATURE			SIGNATURE			

When re-inspection is requested, a complete copy of this report should be ready reviewed by the inspector

Saudi Aramco: Company General Use

SAUDI ARAMCO INSPECTION CHECKLIST MOBILE / CRAWLER CRANES	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-**Jan**-23	DISCIPLINE **ELEVATING/LIFTING EQUIPMENT**
PROJECT TITLE Yanbu Refinery	WBS/BI/JO NUMBER JOB2026-7544	INSPECTION COMPANY **TÜV SÜD for Safety Engineering**	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.:
SRC-STC-050-090	Truck Mounted Crane		TC2050CG0306	TS-YA-26-13619
CAPACITY (SWL) 50 tonne	MANUFACTURER SANY 2026		FACILITY / LOCATION Yanbu.Nesma Yard/Yanbu Refinery	
REQUESTED INSPECTION DATE 21/Sep/2026	**RFI No.**	**TASK COMPLETED DATE** 29/Sep/2026	**EQUIPMENT OWNER** Sudhir Equipment Rental Company	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
1	**GENERAL REQUIREMENTS**					
1.1	Equipment documentation is available	ASME B30.5 Sec:5-2.1.5	✓			
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	✓			
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	✓			
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	✓			Model 2024
1.5	Durable load chart is provided in an accessible location	ASME B30.5 Sec: 5-1.1.3 (b)	✓			
1.6	Work areas chart is available	G.I. 7.025 ASME B30.5 Sec 5-1.1.3(2)	✓			
1.7	Operator is certified (for the inspected crane type/model) and licensed	G.I. 7.025 ASME B30.5 Sec: 5-3.1.1	✓			
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	SAES-B067 Sec:4.4	✓			
1.9	Crane is painted safety yellow	SAES-B067 Sec:4.4	✓			
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067 Sec:4.4			✓	Working in onshore
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067 Sec:4.4	✓			
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5 Sec: 5-3.4.10	✓			
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5 Sec:5-1.6.1-1 Sec:5-1.6.1-2	✓			
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5 Sec:5-1.2.1	✓			
2	**INSPECTION POINTS (MOBILE & CRAWLER CRANES)**					
2.1	Load- holding check valve for boom is operational	ASME B30.5 Sec:5-1.3.1 (d)	✓			
2.2	Two (2) Two (2) full wraps of rope remain on the drum when hook is in the extreme low positionfull wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5 Sec:5-1.3.1	✓			
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5 Sec:5-1.4.1	✓			

SAUDI ARAMCO INSPECTION CHECKLIST MOBILE / CRAWLER CRANES	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-**Jan**-23	DISCIPLINE **ELEVATING/LIFTING EQUIPMENT**
PROJECT TITLE Yanbu Refinery	WBS/BI/JO NUMBER JOB2026-7544	INSPECTION COMPANY **TÜV SÜD for Safety Engineering**	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.:
SRC-STC-050-090	Truck Mounted Crane		TC2050CG0306	TS-YA-26-13619
CAPACITY (SWL) 50 tonne	MANUFACTURER SANY 2026		FACILITY / LOCATION Yanbu.Nesma Yard/Yanbu Refinery	
REQUESTED INSPECTION DATE 21/Sep/2026	**RFI No.**	**TASK COMPLETED DATE** 29/Sep/2026	**EQUIPMENT OWNER** Sudhir Equipment Rental Company	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5 Sec: 5-1.4.2	✓			
2.5	Travel controls are properly operating/functioning	ASME B30.5 Sec: 5-1.1.3	✓			
2.6	Auxiliary travel controls function correctly for multiple control-station cranes	ASME B30.5 Sec: 5-1.5.1	✓			
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3			✓	Truck Mounted Crane
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	✓			
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5 Sec: 5-1.6.3	✓			
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5 Sec: 5-1.7.2			✓	Not used
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5 Sec: 5-1.7.4	✓			
2.12	Sheave guards are in place on the lower block	ASME B30.5 Sec: 5-1.7.4	✓			
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5 Sec: 5-1.7.4 (d)	✓			
2.14	All cab glazing are safety glazing material	ASME B30.5 Sec: 5-1.8.1	✓			
2.15	Verify cab doors functionality and condition	ASME B30.5 Sec: 5-1.8.1	✓			
2.16	Seat belt is fitted and in good condition	ASME B30.5 Sec: 5-1.8.1 (f)	✓			
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5 Sec: 5-1.8.2	✓			
2.18	Guard rails are fitted	ASME B30.5 Sec: 5-1.9.7			✓	Not provided
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1			✓	Hydraulic boom elevating cylinder provided
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1			✓	Hydraulic boom elevating cylinder provided
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5 Sec:5-1.9.1	✓			
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5 Sec:5-1.9.1	✓			

SAUDI ARAMCO INSPECTION CHECKLIST MOBILE / CRAWLER CRANES	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-**Jan**-23	DISCIPLINE **ELEVATING/LIFTING EQUIPMENT**
PROJECT TITLE Yanbu Refinery	WBS/BI/JO NUMBER JOB2026-7544	INSPECTION COMPANY **TÜV SÜD for Safety Engineering**	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.:
SRC-STC-050-090	Truck Mounted Crane		TC2050CG0306	TS-YA-26-13619
CAPACITY (SWL) 50 tonne	MANUFACTURER SANY 2026		FACILITY / LOCATION Yanbu.Nesma Yard/Yanbu Refinery	
REQUESTED INSPECTION DATE 21/Sep/2026	**RFI No.**	**TASK COMPLETED DATE** 29/Sep/2026	**EQUIPMENT OWNER** Sudhir Equipment Rental Company	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.23	Boom shut-off or hydraulic reliefs provided for high angle boom condition	ASME B30.5 Sec: 5-1.9.1 (d)	✓			
2.24	Boom length indicator is fitted for telescoping booms ,and is working	ASME B30.5 Sec: 5-1.9.1	✓			
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5 Sec: 5-3.2.3	✓			
2.26	Operation and accuracy of the fitted Load Indicator, RCI or RCL (compare with load chart)	ASME B30.5 Sec: 5-1.9.10.2	✓			
2.27	LMI is fitted, operational and accurate for bool length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	✓			
2.28	Outriggers and jacks are not leaking oil	ASME B30.5 Sec:5-2.1.3	✓			
2.29	Jack is in good operating condition at each outrigger	ASME B30.5 sec: ASME B30.5 Sec:5-2.1.3 (d)	✓			
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5 Sec: 5-1.9.3 (c)			✓	Not provided
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5 Sec: 5-1.9.3 (c)	✓			
2.32	Outrigger jack bolts are fully secure	ASME B30.5 Sec: 5-1.9.3 (b)	✓			
2.33	All road wheel nuts are fully secure	ASME B30.5 Sec: 5-2.1.3(b)	✓			
2.34	All tires are serviceable and without damage or excess wear	ASME B30.5 Sec: 5-2.1.3(k)	✓			
2.35	Fuel tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	✓			
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	✓			
2.37	Underside of chassis shows no obvious faults	ASME B30.5 Sec: 5-2.1.3	✓			
2.38	Outrigger boxes are not cracked	ASME B30.5 Sec: 5-2.1.3	✓			
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.40	Track rod end joints are not worn and are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.41	Axle bolts and nuts are fully secure	ASME B30.5 Sec: 5-2.1.	✓			
2.42	Wheel hub oil seals are not leaking	ASME B30.5 Sec: 5-2.1.3	✓			

SAUDI ARAMCO INSPECTION CHECKLIST MOBILE / CRAWLER CRANES	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-**Jan**-23	DISCIPLINE **ELEVATING/LIFTING EQUIPMENT**
PROJECT TITLE Yanbu Refinery	WBS/BI/JO NUMBER JOB2026-7544	INSPECTION COMPANY **TÜV SÜD for Safety Engineering**	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.:
SRC-STC-050-090	Truck Mounted Crane		TC2050CG0306	TS-YA-26-13619
CAPACITY (SWL) 50 tonne	MANUFACTURER SANY 2026		FACILITY / LOCATION Yanbu.Nesma Yard/Yanbu Refinery	
REQUESTED INSPECTION DATE 21/Sep/2026	**RFI No.**	**TASK COMPLETED DATE** 29/Sep/2026	**EQUIPMENT OWNER** Sudhir Equipment Rental Company	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.43	Brake linings are not oil contaminated	ASME B30.5 Sec: 5-2.1.3	✓			
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5 Sec: 5-2.1.3	✓			
2.45	All chassis cross members are not cracked or corroded	ASME B30.5 Sec: 5-2.1.3	✓			
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5 Sec: 5-2.1.3	✓			
2.48	Ring gear bolts are fully secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5 Sec: 5-2.1.2	✓			
2.50	Engine shows no major oil leakage	ASME B30.5 Sec: 5-2.1.3	✓			
2.51	Radiator does not leak water	ASME B30.5 Sec: 5-2.1.3	✓			
2.52	Rope is free of kinking, crushing, birdcaging, or any other damage resulting in distortion of the rope structure • No more 1 broken wire protruding from the core • There are no reductions from nominal rope diameter of more than 5% For running ropes: • No more than 6 randomly broken wires in 1 lay or 3 broken wires in 1 strand of 1 lay For rotation resistance ropes : • No more than 2 randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters • Evidence of any heat damage from any cause.	ASME B30.5 Sec: 5-2.4.3	✓			
2.53	Main hoist drum mounting bolts are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5 Sec: 5-2.1.3	✓			
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5 Sec: 5-2.1.3	✓			
2.56	Boom heel pin bushes are not worn (rock boom up and down to check this)	ASME B30.5 Sec: 5-2.1.3	✓			

SAUDI ARAMCO INSPECTION CHECKLIST MOBILE / CRAWLER CRANES	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-**Jan**-23	DISCIPLINE **ELEVATING/LIFTING EQUIPMENT**
PROJECT TITLE Yanbu Refinery	WBS/BI/JO NUMBER JOB2026-7544	INSPECTION COMPANY **TÜV SÜD for Safety Engineering**	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.:
SRC-STC-050-090	Truck Mounted Crane		TC2050CG0306	TS-YA-26-13619
CAPACITY (SWL) 50 tonne	MANUFACTURER SANY 2026		FACILITY / LOCATION Yanbu.Nesma Yard/Yanbu Refinery	
REQUESTED INSPECTION DATE 21/Sep/2026	**RFI No.**	**TASK COMPLETED DATE** 29/Sep/2026	**EQUIPMENT OWNER** Sudhir Equipment Rental Company	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.57	Center swivel coupling pipes and hoses do not leak	ASME B30.5 Sec: 5-2.1.3	✓			
2.58	Center swivel coupling bolts are all secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.59	Boom lift cylinder anchor bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3	✓			
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5 Sec: 5-1.7.3(b)	✓			
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5 Sec: 5-1.6.1(e)	✓			
3	**CRANE CAB**					
3.1	Horn and wind speed anemometer are working	ASME B30.5	✓			
3.2	Crane level indicator is fitted and working	ASME B30.5	✓			
3.3	Engine gauges and associated indicators are working	ASME B30.5	✓			
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5	✓			
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5	✓			
3.6	Dead end rope anchor is correctly made with a suitable wedge socket and loop-back termination	ASME B30.5	✓			
3.7	Hook assemblies are equipped with safety latches	G.I. 7.030	✓			
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.5	✓			
3.9	Hook's weight is clearly marked/printed on the hook	ASME B30.5	✓			
3.10	Safe working load of hook is clearly marked on the item	ASME B30.5	✓			
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10	✓			
3.12	Hook is not bent or twisted • Max. bending or twisting not to exceed 10 degrees from plane of unbent hook or as per manufacturer recommendations	ASME B30.10	✓			
3.13	Hook is not distorted in the throat opening • Max. allowable throat opening is 5% not to exceed 1?4 in. (6 mm) compared to new hook, or as per manufacturer recommendations	ASME B30.10	✓			
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10	✓			
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10	✓			

SAUDI ARAMCO INSPECTION CHECKLIST MOBILE / CRAWLER CRANES	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-**Jan**-23	DISCIPLINE **ELEVATING/LIFTING EQUIPMENT**
PROJECT TITLE Yanbu Refinery	WBS/BI/JO NUMBER JOB2026-7544	INSPECTION COMPANY **TÜV SÜD for Safety Engineering**	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.:
SRC-STC-050-090	Truck Mounted Crane		TC2050CG0306	TS-YA-26-13619
CAPACITY (SWL) 50 tonne	MANUFACTURER SANY 2026		FACILITY / LOCATION Yanbu.Nesma Yard/Yanbu Refinery	
REQUESTED INSPECTION DATE 21/Sep/2026	**RFI No.**	**TASK COMPLETED DATE** 29/Sep/2026	**EQUIPMENT OWNER** Sudhir Equipment Rental Company	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10			✓	Not self-locking hook
3.17	Inoperative latch (if provided) — any damaged latch or malfunctioning latch that does not close the hook's throa	ASME B30.10	✓			
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.10	✓			
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.10	✓			
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loop-back termination	ASME B30.10	✓			
3.21	Reverse travel alarm is operational	ASME B30.5	✓			
3.22	Turning signals and indicators are working correctly	ASME B30.5	✓			
3.23	Road lighting, including spotlights, are in good condition and operable	ASME B30.5	✓			
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5	✓			
4.0	**CRAWLER CRANE**					
4.1	Track pads are undamaged and drive chain are tensioned	ASME B30.5			✓	Truck Mounted Crane
4.2	Drive sockets and drive chain tumblers are serviceable	ASME B30.5			✓	Truck Mounted Crane
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5			✓	Truck Mounted Crane
4.4	Track idlers are serviceable	ASME B30.5			✓	Truck Mounted Crane
4.5	Back boom stops are functioning	ASME B30.5			✓	Truck Mounted Crane
4.6	Back A-Frame is in good condition	ASME B30.5			✓	Truck Mounted Crane
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5			✓	Truck Mounted Crane
4.8	Power low lowering is operational	ASME B30.5			✓	Truck Mounted Crane
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5			✓	Truck Mounted Crane
4.10	Boom chords and lacings are undamaged (bent)	ASME B30.5			✓	Truck Mounted Crane
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5			✓	Truck Mounted Crane
4.12	Pendant ropers are showing no broken wires (see no. 48)	ASME B30.5			✓	Truck Mounted Crane

SAUDI ARAMCO INSPECTION CHECKLIST MOBILE / CRAWLER CRANES	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-**Jan**-23	DISCIPLINE **ELEVATING/LIFTING EQUIPMENT**
PROJECT TITLE Yanbu Refinery	WBS/BI/JO NUMBER JOB2026-7544	INSPECTION COMPANY **TÜV SÜD for Safety Engineering**	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.:
SRC-STC-050-090	Truck Mounted Crane		TC2050CG0306	TS-YA-26-13619
CAPACITY (SWL) 50 tonne	MANUFACTURER SANY 2026		FACILITY / LOCATION Yanbu.Nesma Yard/Yanbu Refinery	
REQUESTED INSPECTION DATE 21/Sep/2026	**RFI No.**	**TASK COMPLETED DATE** 29/Sep/2026	**EQUIPMENT OWNER** Sudhir Equipment Rental Company	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
4.13	Operation of steering brakes is satisfactory	ASME B30.5			✓	Truck Mounted Crane
4.14	Main machinery guarding is in place	ASME B30.5			✓	Truck Mounted Crane
4.15	Main clutch is fully operational	ASME B30.5			✓	Truck Mounted Crane
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5			✓	Truck Mounted Crane

REMARKS:

REFERENCE DOCUMENTS:

1- ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes

2- ASME B30.10 - 2019 Issue: Hooks

3- SAES-B067 - 2020 Issue: Safety Identification and Safety Colors

4- SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification


5- SA GI 7.030 - 2023 Issue: Inspection and Testing Requirements for Elevating/Lifting Equipment

Load Tested By (If Applicable):
Name, Signature, & Date:

,

☑ **Inspected** ☐ **Witnessed by 3rd Party Certified Inspector:**

Name, Signature, Certificate No. & Company:



Yousry Ali , 80019211 ,**TÜV SÜD for Safety Engineering**

User Representative:
Name, Signature, & Date:



Shree , 29/Sep/2026

SATISFACTION SURVEY

Thank you for your feedback

#	Question	Answer
1	Did the Service provider Co. provide the right inspectorwith a valid qualification card?	Yes
2	Did the service provider Co. respond for inspection withinthe expected time frame?	Yes
3	Was the inspector wearing the required personal protective(Yes/No)equipment (PPE) during the inspection?	Yes
4	Did the inspection conducted safely and in accordance with Aramco standard?	Yes

TÜV SÜD for Safety Engineering
شركة توف سود لهندسة السلامة
Al Jubail – 31951, Kingdom of Saudi Arabia
Tel +966 13 3612121, Fax No:+966 13 3632555

NO. : TUV-SUD-15804

Equipment No.: SRC-STC-050-090

Equipment S.N: TC2050CG0306

Equipment SWL: 50 tonne

Date Inspected: 29/Sep/2026

Next Inspection Date: 28/Dec/2026

Inspected by: Yousry Ali

Inspector / SAP NO. **80019211**



S.A. INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY

NOTE: THIS STICKER IS INTENDED AND VALID FOR ARAMCO PREMISES AND PROJECTS ONLY