

INSPECTION CERTIFICATE

MANLIFT

CLIENT NAME : SUDHIR EQUIPMENT RENTAL CO		WORK ORDER : WR-YAS-395	
EQUIPMENT DESCRIPTION : MANLIFT WITH STRAIGHT TELESCOPIC BOOM WITH MAXIMUM WORKING HEIGHT OF 40.10 M		CERTIFICATE NO : YAS-CRT-1675	
DATE OF INSPECTION : 02-Aug-2026		STICKER NO : 13346	
PREVIOUS INSPECTION :		NEXT INSPECTION DUE : 01-Feb-2027	
MANUFACTURER : GENIE		PREVIOUS INSPECTION DETAILS :	
SERIAL NO : SX125D-796		MODEL/TYPE : SX-125 XC	
CHECKLIST NO. : 1420		OWNER ID : S40SG-150	
TYPE OF INSPECTION : PERIODIC AND FUNCTIONAL INSPECTION		MANUFACTURED YEAR : 2019	
REFERENCE STANDARDS : BS EN 280-1:2022		LOCATION : RIYADH	
CAPACITY / SWL:	300 KG		
NO OF PERSONS:	2 PERSONS		
TEST LOAD:	N/A		
MAX HORIZONTAL REACH:	24.38 M		
PLATFORM HEIGHT:	38.10 M		
OUTRIGGER:	N/A		
Is this the first examination after installation or assembly at a new site or location ?	☐ Yes ☒ No	Within an interval of Months?	☒ 6 ☐ 12
If the answer to the above question is YES has the equipment been installed correctly ?	☐ Yes ☒ No	In accordance with an examination scheme ?	☐ Yes ☒ No
After the occurrence of exceptional circumstances ?		☐ Yes ☒ No	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)		NONE	
Is the above a defect which is of immediate danger to persons		☐ Yes ☒ No	
Is the above a defect which is not yet but could become a danger to persons:(If YES state the date by when)		NONE	
Particulars of any tests carried out as part of the examination: (If none state NONE)		NONE	
RESULT:	☒ PASS ☐ FAIL	IS THIS EQUIPMENT FIT FOR PURPOSE?	☒ Yes ☐ No
REMARKS/RECOMMENDATION THIS IS TO CERTIFY THAT THE MANLIFT HAS BEEN PERIODICALLY AND FUNCTIONALLY INSPECTED IN ACCORDANCE WITH INTERNATIONALLY RECOGNIZED STANDARDS ON THE INSPECTION DATE. THE EQUIPMENT IS FREE FROM EXTERNAL DAMAGE, AND THE EQUIPMENT IS FOUND TO BE IN SATISFACTORY CONDITION.			
Date Of Report: 2/8/2026			

Approved By : ABDUL HALEEM

Authorized Inspector : AHAMED

WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675
WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675
WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675



WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675
WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675
WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675

WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675
WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675
WORKORDER NO: WR-YAS-395
CERTIFICATE NO: YAS-CRT-1675

Note : This certificate becomes void if the equipment is altered, repaired, or modified without authorization. The equipment owner is solely responsible for safe operation and maintenance. The company accepts no liability for damages or failures arising from negligence, poor maintenance, or conditions not detectable during routine inspection.