



BV No. 0108438

Above Equipment was inspected by Bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic inspection and function test for Boom supported & landing work platform. As per AS S 9000 G17-30 and 192.5 Pass	

RECEIVER NAME: TRAISGER SIGNATURE: [Signature] INSPECTOR NAME: M. [Signature]
BADGE#: TELEPHONE No.: TELEPHONE No.: 18-009