



BV No. 236300

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]

RECEIVER NAME: THASEER SIGNATURE: [Signature] INSPECTOR NAME: VEETH / 8009191
BADGE#: TELEPHONE NO.: 0552228031 TELEPHONE NO.: 0550486094