



Previous Sticker
No. 21-6019 Issued By Ru

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>21-6019</u> Issued By <u>BV</u>
	<u>DMM</u>	<u>OCT 02, 2023</u>		<u>13:30</u>	
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
<u>SUNAR</u>	<u>5285J-680</u>	<u>DMMYARD</u>		☒ Pass ☐ Fail	<u>BV-21-9580</u>
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
<u>JLG</u>	<u>8605J</u>	<u>500 LBS</u>	<u>MEWP</u>	<u>B300014002</u>	<u>APR 01, 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
✓	Periodic inspection and function test for Boom support elevating work platform. AS per AS S. 0801 Co G57.030, and 92.5 - 'Ross' 	

RECEIVER NAME: APJL SIGNATURE: [Signature] INSPECTOR NAME: M. Morales
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 19106