



BV No. 0108428

Above Equipment was inspected by Bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

RECEIVER NAME: THAJSEER SIGNATURE: [Signature] INSPECTOR NAME: H. [Signature]
BADGE#: TELEPHONE No.: TELEPHONE No.: 198829