



Previous Sticker
No. Swivel Issued By

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DAMMAN	SEP 24, 2023		10:30	No. 25704 Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDHJR	SD12ESL-798	DMMYORD		☒ Pass ☐ Fail	BV-21-9563
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
DINGLI	JCPT1212AC	7000LBS	MEWP	B00454	MARCH 23, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Initial Inspection and Function test for SELF PROTECTED Elevating work Plat form AS Per AS S.O.R.M Co GJF.030, MSJ92.6. PASS	

RECEIVER NAME: ART SIGNATURE: [Signature] INSPECTOR NAME: M. O. M. S. B.
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 19106