



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

Date of thorough examination : 02-06-2025		Date of issue : 02-06-2025		Report No. : ESICO-LFT-R25-4064	
Name & Address of employer		Location		Sticker No	
SUDHIR EQUIPMENT RENTALS		RIYADH		5716	
Equipment Identification No		Equipment Description		Safe Working Load(s)	
S28SJ-1723 OR B300027798		MAN LIFT TYPE: TELESCOPIC MODEL: 860SJ Max.platform height: 26.21m Max.wind speed:12.5m/s Max.manual force:400N Max.occupation person: 2		2024	
Is this the first examination after installaton or assembly at a new site or location?		Yes - No ☒		Was the examination carried out within an interval of? - 6 Months	
If the answer to the above question is YES, has the equipment been installed correctly?		Yes - No -		In accordance with an examination scheme? Yes ☒ No -	
				After the occurence of exceptional circumstances? Yes - No ☒	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE					
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?				N/A	
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)				Yes by : N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A					
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE					
Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory					



For confirmation scan QR code
search with report number : ESICO-LFT-R25-4064



☒ Safe to operate
Next Inspection : 01-12-2025

Inspected by : Mohamed Askar Ali

