

**ENGINEERING CORNER for INSPECTION**

P.O.Box 235, Rastanura 31941 Kingdom of Saudi Arabia

Tel. No's : (013)667 6999/6676895 Fax#:(013)667 6894

Email: Address: eci@eccgroupksa.com / info@eccgroupksa.com / Website : www.eccgroupksa.com



LIFTING EQUIPMENT INSPECTION REPORT	Area: PKG # 4, FIG, FADHILI		CRM No. N/A	RPO No: N/A	No: 031158	
			Inspection Date: 19-Jan-2026	Inspection Time:10.30 AM	No. 24-5248	Issued by: B.v
Department/Contractor SUDHIR EQUIPMENT RENTAL COMPANY	Equipment No. SRC-STC-050-031		Equipment Location: PKG # 4, FIG, FADHILI	Inspection Result : Pass	New sticker No. 32529	
Manufacturer: SANY	Model: STC500T5	Capacity: 50 t	Type: MOBILE CRANE/TRUCK MOUNTED	Equipment S.No. TC2050CE1420	Sticker Expiration 18-Apr-2026	

Above Equipment was inspected by Engineering Corner for Inspection in accordance with applicable Saudi Aramco Gi's, ASME and ANSI Standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency Should be Noted in the corrective action taken column.

NO.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	TRUCK MOUNTED CRANE PERIODIC VISUAL INSPECTION AND FUNCTIONAL TEST PERFORMED PASSED AS PER ARAMCO G.I.7.030 AND ASME B30.5 STANDARD.	
	Note: USED 50 t MAIN HOOK BLOCK WITH 4 PART LINES & 5 t AUX HOOK FITTED AT THE TIME OF INSPECTION.	
	PLATE # 2369 TAA	

USER NAME: Sharyar ahemd

TECHNICAL REVIEWER NAME: ALVARO

Received Date: 19-Jan-2026

SIGNATURE

Reviewed Date: 19-Jan-2026

INSPECTOR NAME: ABDUL KHADER, 80019238

SIGNATURE

BADGE#: 2528217355 TELEPHONE No. 0533677682

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 52	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-050-031	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC2050CE1420	REPORT No 031158
CAPACITY (SWL) 50 t	MANUFACTURER SANY		FACILITY / LOCATION PKG # 4, FIG, FADHILI	
REQUESTED INSPECTION DATE 19-Jan-2026	RFI No	TASK COMPLETED DATE 19-Jan-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
1.0	GENERAL REQUIREMENTS					
1.1	Equipment documentation is available	ASME B30.5 Sec:5-2.1.5	☒	☐	☐	
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	☒	☐	☐	
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	☒	☐	☐	
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	☒	☐	☐	
1.5	Durable load chart is provided in an accessible location	ASME B30.5 Sec: 5-1.1.3 (b)	☒	☐	☐	
1.6	Work areas chart is available	G.1.7,025ASME B30.5 Sec 5-1.1.3(2)	☒	☐	☐	
1.7	Operator is certified (for the inspected crane type/model) and licensed	G.I. 7.025 ASME B30.5 Sec: 5-3.1.1	☒	☐	☐	
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	SAES-B067 Sec:4.4	☒	☐	☐	
1.9	Crane is painted safety yellow	SAES-B067 Sec:4.4	☐	☐	☒	
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067 Sec:4.4	☐	☐	☒	
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067 Sec:4.4	☒	☐	☐	
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5 Sec: 5-3.4.10	☒	☐	☐	
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5 Sec:5-1.6.1-1 Sec:5-1.6.1-2	☒	☐	☐	
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5 Sec:5-1.2.1	☒	☐	☐	
2.0	INSPECTION POINTS (MOBILE & CRAWLER CRANES)					
2.1	Load- holding check valve for boom is operational	ASME B30.5 Sec:5-1.3.1 (d)	☒	☐	☐	
2.2	Two (2) full wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5 Sec:5-1.3.1	☒	☐	☐	
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5 Sec:5-1.4.1	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 52	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-050-031	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC2050CE1420	REPORT No 031158
CAPACITY (SWL) 50 t	MANUFACTURER SANY		FACILITY / LOCATION PKG # 4, FIG, FADHILI	
REQUESTED INSPECTION DATE 19-Jan-2026	RFI No	TASK COMPLETED DATE 19-Jan-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5 Sec: 5-1.4.2	☒	☐	☐	
2.5	Travel controls are properly operating/functioning	ASME B30.5 Sec: 5-1.1.3	☒	☐	☐	
2.6	Auxiliary travel controls function correctly for multiple control- station cranes	ASME B30.5 Sec: 5-1.5.1	☐	☐	☒	
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	☐	☐	☒	
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	☒	☐	☐	
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5 Sec: 5-1.6.3	☐	☐	☒	
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5 Sec: 5-1.7.2	☐	☐	☒	
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5 Sec: 5-1.7.4	☒	☐	☐	
2.12	Sheave guards are in place on the lower block	ASME B30.5 Sec: 5-1.7.4	☒	☐	☐	
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5 Sec: 5-1.7.4 (d)	☒	☐	☐	
2.14	All cab glazings are safety glazing material	ASME B30.5 Sec: 5-1.8.1	☒	☐	☐	
2.15	Verify cab doors functionality and condition	ASME B30.5 Sec: 5-1.8.1	☒	☐	☐	
2.16	Seat belt is fitted and in good condition	ASME B30.5 Sec: 5-1.8.1 (f)	☒	☐	☐	
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5 Sec: 5-1.8.2	☒	☐	☐	
2.18	Guard rails are fitted	ASME B30.5 Sec: 5-1.9.7	☐	☐	☒	
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☐	☐	☒	
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☐	☐	☒	
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 52	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-050-031	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC2050CE1420	REPORT No 031158
CAPACITY (SWL) 50 t	MANUFACTURER SANY		FACILITY / LOCATION PKG # 4, FIG, FADHILI	
REQUESTED INSPECTION DATE 19-Jan-2026	RFI No	TASK COMPLETED DATE 19-Jan-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.23	Boom shut-off or hyraulic relief is provided for high angle boom condition	ASME B30.5 Sec: 5-1.9.1 (d)	☒	☐	☐	
2.24	Boom length indicator is fitted for telescoping booms ,and is working	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5 Sec: 5-3.2.3	☒	☐	☐	
2.26	Operation and accuracy of the fitted Load Indicator, RCI or RCL (compare with load chart)	ASME B30.5 Sec: 5-1.9.10.2	☒	☐	☐	
2.27	LMI is fitted, Operational and accurate for boom length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	☒	☐	☐	
2.28	Outriggers and jacks are not leaking oil	ASME B30.5 Sec:5-2.1.3	☒	☐	☐	
2.29	Jack is in good operating condition at each outrigger	ASME B30.5 Sec:5-2.1.3 (d)	☒	☐	☐	
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5 Sec: 5-1.9.3 (c)	☒	☐	☐	
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5 Sec: 5-1.9.3 (c)	☒	☐	☐	
2.32	Outrigger jack bolts are fully secure	ASME B30.5 Sec: 5-1.9.3 (b)	☒	☐	☐	
2.33	All road wheel nuts are fully secure	ASME B30.5 Sec: 5-2.1.3(b)	☒	☐	☐	
2.34	All tyres are serviceable and without damage or excess wear	ASME B30.5 Sec: 5-2.1.3(k)	☒	☐	☐	
2.35	Fuel tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	☒	☐	☐	
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	☒	☐	☐	
2.37	Underside of chassis shows no obvious faults	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.38	Outrigger boxes are not cracked	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.40	Track rod end joints are not worn and are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.41	Axle bolts and nuts are fully secure	ASME B30.5 Sec: 5-2.1.	☒	☐	☐	
2.42	Wheel hub oil seals are not leaking	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 52	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-050-031	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC2050CE1420	REPORT No 031158
CAPACITY (SWL) 50 t	MANUFACTURER SANY		FACILITY / LOCATION PKG # 4, FIG, FADHILI	
REQUESTED INSPECTION DATE 19-Jan-2026	RFI No	TASK COMPLETED DATE 19-Jan-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.43	Brake linings are not oil contaminated	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.45	All chassis cross members are not cracked or corroded	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.48	Ring gear bolts are fully secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5 Sec: 5-2.1.2	☒	☐	☐	
2.50	Engine shows no major oil leakage	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.51	Radiator does not leak water	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.52	Rope is free of kinking,crushing,birdcaging,or any other damage resulting in distortion of the rope structure .No more 1 broken wire protruding from the core .There are no reductions from nominal rope diameter of more than 5% for running ropes: .No more than 6 randomly broken wires in 1 lay or 3 broken wires in 1 for strand of 1 lay rotation resistance ropes .No more then 2randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters .Evidence of any heat damage from any cause.	ASME B30.5 Sec: 5-2.4.3	☒	☐	☐	
2.53	Main hoist drum mounting bolts are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.56	Boom heel pin bushes are not worn (rock boom up and down to check this)	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.57	Center swivel coupling pipes and hoses do not leak	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.58	Center swivel coupling bolts are all secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 52	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-050-031	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC2050CE1420	REPORT No 031158
CAPACITY (SWL) 50 t	MANUFACTURER SANY		FACILITY / LOCATION PKG # 4, FIG, FADHILI	
REQUESTED INSPECTION DATE 19-Jan-2026	RFI No	TASK COMPLETED DATE 19-Jan-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.59	Boom lift cylinder anchor bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5 Sec: 5-1.7.3(b)	☒	☐	☐	
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5 Sec: 5-1.6.1(e)	☒	☐	☐	
3	CRANE CAB					
3.1	Horn and wind speed anemometer are working	ASME B30.5 Sec: 5-3.2.1.6	☒	☐	☐	
3.2	Crane level indicator is fitted and working	ASME B30.5 Sec: 5-1.9.10.6	☒	☐	☐	
3.3	Engine gauges and associated indicators are working	ASME B30.5 Sec: 5-2.1.3 (g)	☒	☐	☐	
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5 Sec: 5-1.9.12(g)	☒	☐	☐	
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5 Sec: 5-2.1.3 (c)	☒	☐	☐	
3.6	Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	ASME B30.5 Sec: 5-1.7.3 (d)	☒	☐	☐	
3.7	Hook assemblies are equipped with safety latches	ASME B30.5 Sec: 5-1.7.6	☒	☐	☐	
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.10 Sec : 10-1.8	☒	☐	☐	
3.9	Hooks weight is clearly marked/printed on the hook	ASME B30.10 Sec: 10-1.10.5 (b)	☒	☐	☐	
3.10	Safe working load of hook is clearly marked on the item	ASME B30.10 Sec : 10-1.8	☒	☐	☐	
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10 Sec : 10-1.10.5 (d)	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 52	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-050-031	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC2050CE1420	REPORT No 031158
CAPACITY (SWL) 50 t	MANUFACTURER SANY		FACILITY / LOCATION PKG # 4, FIG, FADHILI	
REQUESTED INSPECTION DATE 19-Jan-2026	RFI No	TASK COMPLETED DATE 19-Jan-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
3.12	Hook is not bent or twisted. Max. bending or twisting not to exceed 10 degrees from plane of unbent hook or as per manufacturer recommendations.	ASME B30.10 Sec : 10-1.10.5 (f)	☒	☐	☐	
3.13	Hook is not distorted in the throat opening. .Max allowable throat opening is 5% not to exceed 1/4 in.(6mm) compared to new hook,or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (g)	☒	☐	☐	
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (e)	☒	☐	☐	
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10 Sec : 10-1.10.5 (d)	☒	☐	☐	
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10 Sec : 10-1.10.5 (h)	☐	☐	☒	
3.17	Inoperative latch (if provided) $\frac{1}{2}$ any damaged latch or malfunctioning latch that does not close the hooks throat	ASME B30.10 Sec : 10-1.10.5 (i)	☒	☐	☐	
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.5 Sec:5-1.7.4	☒	☐	☐	
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.5 Figure 5-1.7.3-1	☒	☐	☐	
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loopback termination	ASME B30.5 Figure 5-1.7.3-1	☒	☐	☐	
3.21	Reverse travel alarm is operational.	General	☒	☐	☐	
3.22	Turning signals and indicators are working correctly	General	☒	☐	☐	
3.23	Road lighting, including spotlights, are in good condition and operable	General	☒	☐	☐	
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5 Sec 5-1.9.8	☒	☐	☐	
4.0	CRAWLER CRANE					
4.1	Track pads are undamaged	ASME B30.5 Sec: 5-2.1.3 (h)	☐	☐	☒	
4.2	Drive sockets and tumblers are serviceable	ASME B30.5 Sec: 5-2.1.3 (h)	☐	☐	☒	
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.4	Track idlers are serviceable	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 52	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-050-031	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC2050CE1420	REPORT No 031158
CAPACITY (SWL) 50 t	MANUFACTURER SANY		FACILITY / LOCATION PKG # 4, FIG, FADHILI	
REQUESTED INSPECTION DATE 19-Jan-2026	RFI No	TASK COMPLETED DATE 19-Jan-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
4.4	Track idlers are serviceable	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.5	Back boom stops are functioning	ASME B30.5 Sec: 5-1.9.1 (a)	☐	☐	☒	
4.6	Back A-Frame is in good condition	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5 Sec: 5-1.9.1 (a-2)	☐	☐	☒	
4.8	Power low lowering is operational	ASME B30.5 Sec: 5-1.9.1 (a-2)	☐	☐	☒	
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5 Sec: 5-1.3.1(c)	☐	☐	☒	
4.10	Boom chords and lacings are undamaged (bent)	ASME B30.5 Sec: 5-2.1.3	☐	☐	☒	
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5 Sec: 5-1.7.4 (a)	☐	☐	☒	
4.12	Pendant ropes are showing no broken wires (see no. 48)	ASME B30.5 Sec: 5-2.4.2	☐	☐	☒	
4.13	Operation of steering brakes is satisfactory	ASME B30.5 Sec: 5-1.5.3	☐	☐	☒	
4.14	Main machinery guarding is in place	ASME B30.5 Sec: 5-1.6.4	☐	☐	☒	
4.15	Main clutch is fully operational	ASME B30.5 Sec: 5-1.6.4	☐	☐	☒	
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5 Sec: 5-1.3.2(a-1)	☐	☐	☒	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 52	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-050-031	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC2050CE1420	REPORT No 031158
CAPACITY (SWL) 50 t	MANUFACTURER SANY		FACILITY / LOCATION PKG # 4, FIG, FADHILI	
REQUESTED INSPECTION DATE 19-Jan-2026	RFI No	TASK COMPLETED DATE 19-Jan-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

Remarks:	
Reference Documents 1- ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes 2- ASME B30.10 - 2019 Issue: Hooks 3- SAES-B067 - 2020 Issue: Safety Identification and Safety Colors 4- SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification	
Load Tested By (if Applicable): Name, Signature, & Date:	
Inspected Witnessed by 3rd Party Certified Inspector: Name, Signature, Certificate No. & Company: ABDUL KHADER, 80019238	
User Representative: Name, Signature, & Date: Sharyar ahemd & 19-Jan-2026	



Engineering Corner for Inspection Co. Ltd. (ECI)

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.:(013)667-6999 / 667-6895 - Fax:(013)667-6894

E-mail: eci@eccgroupksa.com

No. **ECI - 32529**

EQUIP.S.N.: TC2050CE1420

EQUIP. NO.: SRC-STC-050-031

EQUIP SWL: 50 t

INSPECTION DATE : 19-Jan-2026

NEXT INSPECTION DATE : 18-Apr-2026

INSPECTOR NAME : ABDUL KHADER

SAP# : 80019238

"S.A. INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY"

	ENGINEERING CORNER for INSPECTION		Doc. No.	ECIR- LFT - 105
			Rev. No	01
	CUSTOMER FEEDBACK FORM - LFT & ELEV		Rev. Date	1 NOV 2025
			Page No.	1 of 1

Issue Number : 02 & Issue Date : 03 FEB 2020

Feedback Form Number: 031158

Customer Details:

Client Name	SUDHIR EQUIPMENT RENTAL COMPANY	Contact Person Name	Sharyar ahemd
Client Address	PKG # 4, FIG, FADHILI	Department	2528217355
Email ID	logistics@sudhirrentals.com	Contact Number	0533677682
Inspection Date	19/01/2026	Inspector Name	ABDUL KHADER

Dear Sir/Madam,

We request you to kindly put a 'TICK' mark in the respective boxes against each aspect described below and to assess your feedback with respect to the service we have provided so far. Any other suggestion or remarks please indicate the same to improve further. Thank you for taking your time for giving your valuable feedback to us.

Description	Yes	No	Remarks
Did the Service provider Co. provide the right inspector with a valid qualification card?	☒		
Did the Service provider Co. respond for inspection within the expected time frame?	☒		
Was the inspector wearing the required personal protective equipment (PPE) during the inspection?	☒		
Did the inspection conducted safely and in accordance with Aramco's standards?	☒		
How satisfied are you with the overall service provided? * * * * *			
Would you consider using this Service Provider again for future inspections? * * * * *			
For any enquiry or concern, please contact: Inspection Dept. - ISSD Crane Inspection Unit (CIU)			

Any suggestions for improvement or additional services required?	Feedback given by (Customer Representative)
	