

OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

Equipment	Crane
Brand / Make	SANY
Asset ID	SRC-STC-110-021
Model Number	STC1100T7
Serial Number	TC0110CE0610
Capacity	110 TON
Type	Sany Truck Crane
Manufacturing Year	2024

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : Info@sudhirrentals.com

Sincerely,

Ajay Koul
General Manager
Sudhir Equipment Rental Company





بروج للتأمين التعاوني
Buruj Cooperative Insurance

شهادة التأمين - CERTIFICATE OF INSURANCE

Policy Holder Name	:	Sudhir Equipment Rental Company	:	اسم حامل الوثيقة
Policy Number	:	01/CPM/ 2025/000002	:	رقم الوثيقة
Policy Period	:	05/04/ 2025 to 04/04/2026	:	فترة الوثيقة
Description of Machinery / Equipment	:	SANY-CRANES-STC1100T7	:	وصف المعدة/ال لة
Chassis / Serial No.	:	TC0110CE0610	:	رقم الهيكل/ التسلسلي
Year of Manufacturing	:	2024	:	سنة الصنع
Asset ID No.	:	SRC-STC-110-021	:	رقم ال صل
Location	:	Kingdom of Saudi Arabia.	:	الموقع

BURUJ Cooperative Insurance Company certifies that above client is holding a Machinery/Equipment Insurance Policy for the above-mentioned Equipment in accordance with the above-mentioned Insurance Policy.

With effect from: 05/04/ 2025 to 04/04/2026

This Certificate has been issued upon Insured's request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تشهد شركة بروج للتأمين التعاوني بأن السادة أعل ه مؤمنين لديها تأمين المكان/المعدات المذكورة أعل ه وذلك حسب وثيقة التأمين المذكورة أعل ه

والتي يبدأ تاريخ سريانها من ٢٠٢٥/٠٤/٠٥ إلى ٢٠٢٦/٠٤/٠٤

تم إصدار هذه الشهادة بناءً على طلب المؤمن له وذلك حسب الشروط وال استثناءات وال شتراطات المذكورة في الوثيقة.

Important Notices:

1. This Certificate does not pay any fines, penalties, bonds or cautions that may be imposed.
2. Original certificates are only accepted.
3. Due to the importance of correct information being stated in this certificate, kindly examine the document carefully and advise the Company of any difference.
4. In the event of changes in the above information, kindly contact +966-11-2938383

مل حظات هامة:

- ١) ل تطبق هذه الشهادة التأمين على الغرامات والعقوبات المالية بما في ذلك المخالفات أو الضمانات أو الكفالات التي قد تقرر.
- ٢) تقبل الشهادة ال صلية فقط.
- ٣) نظراً ل همية صحة البيانات الخاصة بكم في هذه الشهادة، الرجاء التأكد منها وإشعار الشركة في حالة وجود أي اختل فات.
- ٤) عند الحاجة إلى تعديل البيانات أعل ه يرجى ال اتصال على شركة بروج للتأمين التعاوني ٢٩٣٨٣٨٣-١١-٩٦٦+



BURUJ Cooperative Insurance Company

P.O. Box 51855, Riyadh 11553,
National Address 3385, Al Thomamah Road, An-Nada District.
800 124 0201 | burujinsurance.com

Issue Date: 3 April 2025

KINGDOM OF SAUDI ARABIA
MINISTRY OF INTERIOR

رخصة سير
VEHICLES REGISTRATION

المملكة العربية السعودية
وزارة الداخلية

المالك شركة سودهير لتأجير المعدات شركة الشخص الواحد
المستخدم

هوية المالك ٧٠١٦١٥٨٣٣٤ هوية المستخدم

رقم الهيكل LFCNRG7P8P3200528

رقم اللوحة ٣٧٧٧ أ أ أ

نوع التسجيل اشغال عامة 3777 A A A

ماركة المركبة ساني طراز المركبة كرين

حمولة المركبة ٢ وزن المركبة ٥٤٦

سنة الصنع ٢٠٢٤ اللون ابيض / ازرقي

الرقم التسلسلي ٧٣٧٢٧٩٠٢٠



تفاصيل المركبة

① إرسال طلب تحديث مركبة

رقم هوية المالك	7016158334	تاريخ بداية الملكية					
تاريخ اصدار رخصة السير	1445-12-27	تاريخ إنتهاء رخصة السير	1448-12-27				
رقم الفرع		اسم الفرع					
رقم هوية المستخدم الفعلي		اسم المستخدم الفعلي					
نوع تسجيل اللوحة	معدات ثقيلة	معلومات اللوحة	<table><tr><td>١١١</td><td>٣٧٧٧</td></tr><tr><td>٨٨٨</td><td>٣٧٧٧</td></tr></table>	١١١	٣٧٧٧	٨٨٨	٣٧٧٧
١١١	٣٧٧٧						
٨٨٨	٣٧٧٧						
الرقم التسلسلي	737279020	صانع المركبة	ساني				
طراز المركبة	كرين	لون المركبة	أزرق				
الحمولة	2	الوزن	54600				
سنة الصنع	2024	حالة التخفظ	غير متحفظ				
رقم الهيكل	LFCNRG7P8P3200528	وضع المركبة	صالحة				
حالة الفحص الدوري	لا يوجد	تاريخ انتهاء الفحص الدوري بالهجري					
حالة التأمين	ساري المفعول	تاريخ إنتهاء التأمين	2025-11-14				
تاريخ بدء المستخدم الفعلي							



Development Member

Certificate of Thorough Examination
This certificate meets the Lifting Equipment Engineers Association Technical requirements

Company Name & Address: **Universal Inspection Co. Ltd/ Al- Jubail**

Report No: **UIC-DAM-2025-03-155**

Crane No.: **SRC-RT-050-042**

Date of Report: **19-MAR-2025**

Colour code (if required): **NR**

Name & Address of the employer for whom the examination was made: Sudhir Equipment Rental Company						Address of the premises at which the examination was made: Dammam, Kingdom of Saudi Arabia.				Status: ND – No Defect; SDR – See Defect Report NF – Not Found	
Identification Number	Description	WLL or SWL	Length/Size	Date of Last Thorough Examination	Date of Thorough Examination	Date of next thorough Examination	Reason for Examination (See Below)	Ref. Standard	Details of any test	Status (See above)	Safe to Use Yes or No
60079720	Wire Rope Sling	2.8 Ton	1.6 m/ 18 mm	N/A	19-MAR-2025	18-SEP-2025	B	ASME B30.9	N/A	ND	YES
AM-1390-05	Wire Rope Sling	4.1 Ton	1.5 m/ 18 mm	N/A	19-MAR-2025	18-SEP-2025	B	ASME B30.9	N/A	ND	YES
Reason for Examination	Installation: A		6 Monthly: B		12 Monthly: C		Written Scheme: D		Exceptional Circumstance: E		
Name of the person making this report: MOHAMED WASIM M						Name of the person authenticating this report: ABDUL KHALEEL					
						Signature: 					



Page | 1 of 1



Development Member

Certificate of Thorough Examination
This certificate meets the Lifting Equipment Engineers Association Technical requirements

Company Name & Address: **Universal Inspection Co. Ltd/ Al- Jubail**

Report No: **UIC-DAM-2025-03-156**

Crane No: **SRC-RT-050-042**

Date of Report: **19-MAR-2025**

Colour code (if required): **NR**

Name & Address of the employer for whom the examination was made: Sudhir Equipment Rental Company						Address of the premises at which the examination was made: 2nd Industry Dammam, Kingdom of Saudi Arabia.				Status: ND – No Defect: SDR – See Defect Report NF – Not Found	
Identification Number	Description	WLL or SWL	Length/Size	Date of Last Thorough Examination	Date of Thorough Examination	Date of next thorough Examination	Reason for Examination (See Below)	Ref. Standard	Details of any test	Status (See above)	Safe to Use Yes or No
M-8187	Bow Shackle	4 Ton	25 mm	N/A	19-MAR-2025	18-SEP-2025	B	ASME B30.26	N/A	ND	YES
M-8188	Bow Shackle	4 Ton	25 mm	N/A	19-MAR-2025	18-SEP-2025	B	ASME B30.26	N/A	ND	YES
Reason for Examination	Installation: A		6 Monthly: B		12 Monthly: C		Written Scheme: D		Exceptional Circumstance: E		
Name of the person making this report: MOHAMED WASIM						Name of the person authenticating this report: ABDUL KHALEEL					
						Signature:					



Page | 1 of 1



CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF MOBILE CRANE

Cert. No.: 1726174	Date of Examination: 29/08/2024	Sticker No.: 24-1744 Load test
---------------------------	--	---------------------------------------

Name & address of owner of the equipment		SUDHIR EQUIPMENT RENTAL CO.
Inspection requested by		SUDHIR EQUIPMENT RENTAL CO.
Place of inspection		DMM YARD
Type of inspection		TEST & THOROUGH EXAMINATION
Relevant regulation / Standard		ASME B30.5
Date of previous inspection / load test		29/08/2024 Not applicable
Identification & Description of the Equipment	Manufacturer name	SANY
	Equipment Type	RT MOBILE CRANE
	Nature of power	DEISEL POWERED
	Model / Year	STC110T7
	Serial number	TC0110CE0610
	Owner ID / Registration number	SRC-STC-110-021
	Rated Capacity (maximum)	110 TON
	Present Configuration	Main hoist current capacity: 100 TON with 6 FALLS Auxiliary hoist current capacity: 8 TON with 1
	Radius (Mini / Max)	Minimum: 3 m; Maximum: 64 m
	Length of Boom	Minimum: 14.1 m; Maximum: 75.5 m
	Counterweight (mass)	Standard from Manufacturer
	Wire rope specification	22 mm
Complementary devices		FLY JIB WAS STOWED

Description of test: -Visual inspection was carried out, followed by full functional testing. -100 % OF SWL LOAD TEST WAS APPLIED Note: "This certificate does not cover the use of the equipment for Personnel/Man riding purposes".	Length of boom (m)	Radius (m)	Reeving (No. of falls)	Test Load	Safe Working Load
	37.7 m	18 m	6 falls	19400 kg	19400 kg
	-	-	-	-	-
	-	-	-	-	-

Result of Examination:

The above mentioned equipment has been found satisfactory at the time of inspection and is considered to be safe for further use, subject to continuous maintenance being applied and qualified operator being employed.

This is to certify that the Competent Person did attend at the said premises on said date to witness proof load test and/or to carry out thorough examination of the equipment described herein and that all particulars described above were correct at the time of examination. This Certificate becomes void in case of any major repair, modification and / or alteration being un-authorized by issuer of hereof.

Next Proof Load Test Due: 28/08/2029 or After Major Repair/Modifications	Next Inspection Due is on or before: 28/11/2024
---	--

Issued at Al Khobar on 29/08/2024

Inspector to Bureau Veritas
Signature:



Name: Mohamed OMARA
Position: Senior Inspector



Reviewed by
Signature:



Name: Abdullah SHEHRI
Position: Operations Manager

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.

This not is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacture, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.



CHECKLIST OF TEST & THOROUGH EXAMINATION OF MOBILE CRANE

Cert. No.: 1726174	Date of Examination: 29/08/2024
---------------------------	--

SECTION	CONDITION	REMARKS
1. ACCESS		
1.1 Access to the cabin/control station	Satisfactory	
1.2 Access for maintenance operation	Satisfactory	
2. CHASSIS		
2.1 Chassis	Satisfactory	
2.2 Traveling device (tire, crawler)	Satisfactory	
2.3 Outriggers	Satisfactory	
2.4 Outrigger sole (shoe or pad)	Satisfactory	
2.5 None return valve on outrigger	Satisfactory	
2.6 Locking of suspensions	Satisfactory	
2.7 Locking of outriggers rest position	Satisfactory	
3. STRUCTURE OF EQUIPMENT		
3.1 Structure, A frame	Satisfactory	
3.2 Jib, fly jib	Satisfactory	STOWED
3.3 Pendants	Not applicable	
3.4 Counter weight	Satisfactory	
4. MECHANISM		
4.1 Main Hoisting mechanism	Satisfactory	
4.2 Aux. Hoisting mechanism	Satisfactory	
4.3 Hydraulic system	Satisfactory	
4.4 Cylinders	Satisfactory	
4.5 Hoisting brake system	Satisfactory	
4.6 Limitation of the lowering speed	Satisfactory	
4.7 Telescoping mechanism	Satisfactory	
4.8 Luffing mechanism	Not applicable	
4.9 Pivoting joints	Satisfactory	
4.10 Brake of slewing motion	Satisfactory	



4.11 Traveling Brake	Satisfactory	
4.12 Guards for moving parts	Satisfactory	
4.13 Motor	Satisfactory	
4.14 Gear box	Satisfactory	
5. LIFTING SYSTEM		
5.1 Wire rope / chain	Satisfactory	
5.2 Wire/chain rope end termination	Satisfactory	
5.3 Drum, pulley, return pulley	Satisfactory	
5.4 Hooks & hook blocks	Satisfactory	
5.5 Other load handling devices	Satisfactory	
6. ENERGY		
6.1 Main switch locking	Satisfactory	
6.2 Equipment and cabling	Satisfactory	
6.3 Protection of live parts/enclosure	Satisfactory	
6.4 Lighting of the crane/site	Satisfactory	
7. CABIN / CONTROL STATION		
7.1 Structure	Satisfactory	
7.2 Visibility / windows	Satisfactory	
7.3 Heating / AC system	Satisfactory	
7.4 Seat	Satisfactory	
7.5 Fire extinguisher	Satisfactory	
7.6 Identification of the controls	Satisfactory	
7.7 Control dead man type	Satisfactory	
7.8 General stopping device by key	Satisfactory	
7.9 Emergency stop button	Satisfactory	
7.10 Level indicator	Satisfactory	
7.11 Angle Indicator	Satisfactory	
7.12 Horn	Satisfactory	
7.13 Traffic lights	Satisfactory	
7.14 Direction Indicators	Satisfactory	
8. SAFETY DEVICES		



BUREAU
VERITAS



8.1 Hoisting limiter/Anti Two Blocks	Satisfactory	
8.2 Luffing limiter	Not applicable	
8.3 Telescopic limiter	Satisfactory	
8.4 Slewing limiter	Satisfactory	
8.5 Load limiter	Satisfactory	
8.6 Level limiter	Satisfactory	
8.7 Rated capacity indicator (RCI) / ASLI	Satisfactory	
8.8 None return valve on piston	Satisfactory	
8.9 Other limiter or indicator	Satisfactory	
9. MISCELLANEOUS REQUIREMENTS		
9.1 Maker plate	Satisfactory	
9.2 Load chart	Satisfactory	
9.3 Wire rope certificate	Satisfactory	
9.4 General Safety Requirements	Satisfactory	
Notes : - Maintain proper housekeeping & preventive maintenance.		
Next Proof Load Test Due: 28/08/2029 or After Major Repair/Modifications		Next Inspection Due is on or before: 28/11/2024

Inspector to Bureau Veritas
Signature:



Name: Mohamed OMARA
Position: Senior Inspector

**ENGINEERING CORNER for INSPECTION**

P.O.Box 235, Rastanura 31941 Kingdom of Saudi Arabia

Tel. No's : (013)667 6999/6676895 Fax#:(013)667 6894

Email: Address: eci@eccgroupksa.com / info@eccgroupksa.com / Website : www.eccgroupksa.com



LIFTING EQUIPMENT INSPECTION REPORT	Area: ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH		CRM No. N/A	RPO No: N/A	No: 030367	
			Inspection Date: 09-Dec-2025	Inspection Time:10.30 AM	No. 1305	Issued by: B.v
Department/Contractor SUDHAIR RENTALS	Equipment No. SRC-STC-110-021		Equipment Location: ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	Inspection Result : Pass	New sticker No. 31640	
Manufacturer: SANY	Model: STC1100T7	Capacity: 110 t	Type: MOBILE CRANE/TRUCK MOUNTED	Equipment S.No. TC0110CE0610	Sticker Expiration 08-Mar-2026	

Above Equipment was inspected by Engineering Corner for Inspection in accordance with applicable Saudi Aramco Gi's, ASME and ANSI Standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency Should be Noted in the corrective action taken column.

NO.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	TRUCK MOUNTED CRANE PERIODIC VISUAL INSPECTION AND FUNCTIONAL TEST PERFORMED PASSED AS PER ARAMCO G.I.7.030 AND ASME B30.5 STANDARD.	
	Note : USED 100 t MAIN HOOK BLOCK (SL.N: HCZ24100034) WITH 6 PART LINES & 8 t AUX HOOK FITTED (SL.N: YM2023120816) AT THE TIME OF INSPECTION.	
	PLATE NO : 3777 AAA	

USER NAME: Arif shmshad

BADGE#: 2574279309 TELEPHONE No. 0553503143

TECHNICAL REVIEWER NAME: ALVARO

Received Date: 09-Dec-2025

SIGNATURE

Reviewed Date: 09-Dec-2025

INSPECTOR NAME: ABDUL KHADER, 80019238

SIGNATURE

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 3969	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-110-021	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC0110CE0610	REPORT No 030367
CAPACITY (SWL) 110 t	MANUFACTURER SANY		FACILITY / LOCATION ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	
REQUESTED INSPECTION DATE 09-Dec-2025	RFI No	TASK COMPLETED DATE 09-Dec-2025	EQUIPMENT OWNER SUDHAIR RENTALS	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
1.0	GENERAL REQUIREMENTS					
1.1	Equipment documentation is available	ASME B30.5 Sec:5-2.1.5	☒	☐	☐	
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	☒	☐	☐	
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	☒	☐	☐	
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	☒	☐	☐	
1.5	Durable load chart is provided in an accessible location	ASME B30.5 Sec: 5-1.1.3 (b)	☒	☐	☐	
1.6	Work areas chart is available	G.1.7.025ASME B30.5 Sec 5-1.1.3(2)	☒	☐	☐	
1.7	Operator is certified (for the inspected crane type/model) and licensed	G.I. 7.025 ASME B30.5 Sec: 5-3.1.1	☒	☐	☐	
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	SAES-B067 Sec:4.4	☒	☐	☐	
1.9	Crane is painted safety yellow	SAES-B067 Sec:4.4	☐	☐	☒	
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067 Sec:4.4	☐	☐	☒	
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067 Sec:4.4	☒	☐	☐	
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5 Sec: 5-3.4.10	☒	☐	☐	
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5 Sec:5-1.6.1-1 Sec:5-1.6.1-2	☒	☐	☐	
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5 Sec:5-1.2.1	☒	☐	☐	
2.0	INSPECTION POINTS (MOBILE & CRAWLER CRANES)					
2.1	Load- holding check valve for boom is operational	ASME B30.5 Sec:5-1.3.1 (d)	☒	☐	☐	
2.2	Two (2) full wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5 Sec:5-1.3.1	☒	☐	☐	
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5 Sec:5-1.4.1	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 3969	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-110-021	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC0110CE0610	REPORT No 030367
CAPACITY (SWL) 110 t	MANUFACTURER SANY		FACILITY / LOCATION ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	
REQUESTED INSPECTION DATE 09-Dec-2025	RFI No	TASK COMPLETED DATE 09-Dec-2025	EQUIPMENT OWNER SUDHAIR RENTALS	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5 Sec: 5-1.4.2	☒	☐	☐	
2.5	Travel controls are properly operating/functioning	ASME B30.5 Sec: 5-1.1.3	☒	☐	☐	
2.6	Auxiliary travel controls function correctly for multiple control- station cranes	ASME B30.5 Sec: 5-1.5.1	☐	☐	☒	
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	☐	☐	☒	
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	☒	☐	☐	
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5 Sec: 5-1.6.3	☐	☐	☒	
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5 Sec: 5-1.7.2	☐	☐	☒	
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5 Sec: 5-1.7.4	☒	☐	☐	
2.12	Sheave guards are in place on the lower block	ASME B30.5 Sec: 5-1.7.4	☒	☐	☐	
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5 Sec: 5-1.7.4 (d)	☒	☐	☐	
2.14	All cab glazings are safety glazing material	ASME B30.5 Sec: 5-1.8.1	☒	☐	☐	
2.15	Verify cab doors functionality and condition	ASME B30.5 Sec: 5-1.8.1	☒	☐	☐	
2.16	Seat belt is fitted and in good condition	ASME B30.5 Sec: 5-1.8.1 (f)	☒	☐	☐	
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5 Sec: 5-1.8.2	☒	☐	☐	
2.18	Guard rails are fitted	ASME B30.5 Sec: 5-1.9.7	☐	☐	☒	
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☐	☐	☒	
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☐	☐	☒	
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 3969	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-110-021	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC0110CE0610	REPORT No 030367
CAPACITY (SWL) 110 t	MANUFACTURER SANY		FACILITY / LOCATION ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	
REQUESTED INSPECTION DATE 09-Dec-2025	RFI No	TASK COMPLETED DATE 09-Dec-2025	EQUIPMENT OWNER SUDHAIR RENTALS	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.23	Boom shut-off or hyraulic relief is provided for high angle boom condition	ASME B30.5 Sec: 5-1.9.1 (d)	☒	☐	☐	
2.24	Boom length indicator is fitted for telescoping booms ,and is working	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5 Sec: 5-3.2.3	☒	☐	☐	
2.26	Operation and accuracy of the fitted Load Indicator, RCI or RCL (compare with load chart)	ASME B30.5 Sec: 5-1.9.10.2	☒	☐	☐	
2.27	LMI is fitted, Operational and accurate for boom length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	☒	☐	☐	
2.28	Outriggers and jacks are not leaking oil	ASME B30.5 Sec:5-2.1.3	☒	☐	☐	
2.29	Jack is in good operating condition at each outrigger	ASME B30.5 Sec:5-2.1.3 (d)	☒	☐	☐	
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5 Sec: 5-1.9.3 (c)	☒	☐	☐	
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5 Sec: 5-1.9.3 (c)	☒	☐	☐	
2.32	Outrigger jack bolts are fully secure	ASME B30.5 Sec: 5-1.9.3 (b)	☒	☐	☐	
2.33	All road wheel nuts are fully secure	ASME B30.5 Sec: 5-2.1.3(b)	☒	☐	☐	
2.34	All tyres are serviceable and without damage or excess wear	ASME B30.5 Sec: 5-2.1.3(k)	☒	☐	☐	
2.35	Fuel tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	☒	☐	☐	
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	☒	☐	☐	
2.37	Underside of chassis shows no obvious faults	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.38	Outrigger boxes are not cracked	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.40	Track rod end joints are not worn and are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.41	Axle bolts and nuts are fully secure	ASME B30.5 Sec: 5-2.1.	☒	☐	☐	
2.42	Wheel hub oil seals are not leaking	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 3969	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-110-021	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC0110CE0610	REPORT No 030367
CAPACITY (SWL) 110 t	MANUFACTURER SANY		FACILITY / LOCATION ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	
REQUESTED INSPECTION DATE 09-Dec-2025	RFI No	TASK COMPLETED DATE 09-Dec-2025	EQUIPMENT OWNER SUDHAIR RENTALS	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.43	Brake linings are not oil contaminated	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.45	All chassis cross members are not cracked or corroded	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.48	Ring gear bolts are fully secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5 Sec: 5-2.1.2	☒	☐	☐	
2.50	Engine shows no major oil leakage	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.51	Radiator does not leak water	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.52	Rope is free of kinking,crushing,birdcaging,or any other damage resulting in distortion of the rope structure .No more 1 broken wire protruding from the core .There are no reductions from nominal rope diameter of more than 5% for running ropes: .No more than 6 randomly broken wires in 1 lay or 3 broken wires in 1 for strand of 1 lay rotation resistance ropes .No more then 2randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters .Evidence of any heat damage from any cause.	ASME B30.5 Sec: 5-2.4.3	☒	☐	☐	
2.53	Main hoist drum mounting bolts are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.56	Boom heel pin bushes are not worn (rock boom up and down to check this)	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.57	Center swivel coupling pipes and hoses do not leak	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.58	Center swivel coupling bolts are all secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 3969	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-110-021	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC0110CE0610	REPORT No 030367
CAPACITY (SWL) 110 t	MANUFACTURER SANY		FACILITY / LOCATION ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	
REQUESTED INSPECTION DATE 09-Dec-2025	RFI No	TASK COMPLETED DATE 09-Dec-2025	EQUIPMENT OWNER SUDHAIR RENTALS	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.59	Boom lift cylinder anchor bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5 Sec: 5-1.7.3(b)	☐	☐	☒	
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5 Sec: 5-1.6.1(e)	☒	☐	☐	
3	CRANE CAB					
3.1	Horn and wind speed anemometer are working	ASME B30.5 Sec: 5-3.2.1.6	☒	☐	☐	
3.2	Crane level indicator is fitted and working	ASME B30.5 Sec: 5-1.9.10.6	☒	☐	☐	
3.3	Engine gauges and associated indicators are working	ASME B30.5 Sec: 5-2.1.3 (g)	☒	☐	☐	
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5 Sec: 5-1.9.12(g)	☒	☐	☐	
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5 Sec: 5-2.1.3 (c)	☒	☐	☐	
3.6	Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	ASME B30.5 Sec: 5-1.7.3 (d)	☐	☐	☒	
3.7	Hook assemblies are equipped with safety latches	ASME B30.5 Sec: 5-1.7.6	☒	☐	☐	
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.10 Sec : 10-1.8	☒	☐	☐	
3.9	Hooks weight is clearly marked/printed on the hook	ASME B30.10 Sec: 10-1.10.5 (b)	☒	☐	☐	
3.10	Safe working load of hook is clearly marked on the item	ASME B30.10 Sec : 10-1.8	☒	☐	☐	
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10 Sec : 10-1.10.5 (d)	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 3969	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-110-021	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC0110CE0610	REPORT No 030367
CAPACITY (SWL) 110 t	MANUFACTURER SANY		FACILITY / LOCATION ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	
REQUESTED INSPECTION DATE 09-Dec-2025	RFI No	TASK COMPLETED DATE 09-Dec-2025	EQUIPMENT OWNER SUDHAIR RENTALS	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
3.12	Hook is not bent or twisted. Max. bending or twisting not to exceed 10 degrees from plane of unbent hook or as per manufacturer recommendations.	ASME B30.10 Sec : 10-1.10.5 (f)	☒	☐	☐	
3.13	Hook is not distorted in the throat opening. Max allowable throat opening is 5% not to exceed 1/4 in.(6mm) compared to new hook,or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (g)	☒	☐	☐	
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (e)	☒	☐	☐	
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10 Sec : 10-1.10.5 (d)	☒	☐	☐	
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10 Sec : 10-1.10.5 (h)	☐	☐	☒	
3.17	Inoperative latch (if provided) $\frac{1}{2}$ any damaged latch or malfunctioning latch that does not close the hooks throat	ASME B30.10 Sec : 10-1.10.5 (i)	☒	☐	☐	
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.5 Sec:5-1.7.4	☒	☐	☐	
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.5 Figure 5-1.7.3-1	☒	☐	☐	
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loopback termination	ASME B30.5 Figure 5-1.7.3-1	☐	☐	☒	
3.21	Reverse travel alarm is operational.	General	☒	☐	☐	
3.22	Turning signals and indicators are working correctly	General	☒	☐	☐	
3.23	Road lighting, including spotlights, are in good condition and operable	General	☒	☐	☐	
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5 Sec 5-1.9.8	☒	☐	☐	
4.0	CRAWLER CRANE					
4.1	Track pads are undamaged	ASME B30.5 Sec: 5-2.1.3 (h)	☐	☐	☒	
4.2	Drive sockets and tumblers are serviceable	ASME B30.5 Sec: 5-2.1.3 (h)	☐	☐	☒	
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.4	Track idlers are serviceable	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 3969	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-110-021	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC0110CE0610	REPORT No 030367
CAPACITY (SWL) 110 t	MANUFACTURER SANY		FACILITY / LOCATION ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	
REQUESTED INSPECTION DATE 09-Dec-2025	RFI No	TASK COMPLETED DATE 09-Dec-2025	EQUIPMENT OWNER SUDHAIR RENTALS	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
4.4	Track idlers are serviceable	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.5	Back boom stops are functioning	ASME B30.5 Sec: 5-1.9.1 (a)	☐	☐	☒	
4.6	Back A-Frame is in good condition	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5 Sec: 5-1.9.1 (a-2)	☐	☐	☒	
4.8	Power low lowering is operational	ASME B30.5 Sec: 5-1.9.1 (a-2)	☐	☐	☒	
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5 Sec: 5-1.3.1(c)	☐	☐	☒	
4.10	Boom chords and lacings are undamaged (bent)	ASME B30.5 Sec: 5-2.1.3	☐	☐	☒	
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5 Sec: 5-1.7.4 (a)	☐	☐	☒	
4.12	Pendant ropes are showing no broken wires (see no. 48)	ASME B30.5 Sec: 5-2.4.2	☐	☐	☒	
4.13	Operation of steering brakes is satisfactory	ASME B30.5 Sec: 5-1.5.3	☐	☐	☒	
4.14	Main machinery guarding is in place	ASME B30.5 Sec: 5-1.6.4	☐	☐	☒	
4.15	Main clutch is fully operational	ASME B30.5 Sec: 5-1.6.4	☐	☐	☒	
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5 Sec: 5-1.3.2(a-1)	☐	☐	☒	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER 3969	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-STC-110-021	EQUIPMENT DESCRIPTION/TYPE TRUCK MOUNTED		SERIAL NO TC0110CE0610	REPORT No 030367
CAPACITY (SWL) 110 t	MANUFACTURER SANY		FACILITY / LOCATION ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	
REQUESTED INSPECTION DATE 09-Dec-2025	RFI No	TASK COMPLETED DATE 09-Dec-2025	EQUIPMENT OWNER SUDHAIR RENTALS	

Remarks:	
Reference Documents 1- ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes 2- ASME B30.10 - 2019 Issue: Hooks 3- SAES-B067 - 2020 Issue: Safety Identification and Safety Colors 4- SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification	
Load Tested By (if Applicable): Name, Signature, & Date:	
Inspected Witnessed by 3rd Party Certified Inspector: Name, Signature, Certificate No. & Company: ABDUL KHADER, 80019238	
User Representative: Name, Signature, & Date: Arif shmshad & 09-Dec-2025	



Engineering Corner for Inspection Co. Ltd. (ECI)

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.:(013)667-6999 / 667-6895 - Fax:(013)667-6894

E-mail: eci@eccgroupksa.com

No. **ECI - 31640**

EQUIP.S.N.: TC0110CE0610

EQUIP. NO.: SRC-STC-110-021

EQUIP SWL: 110 t

INSPECTION DATE : 09-Dec-2025

NEXT INSPECTION DATE : 08-Mar-2026

INSPECTOR NAME : ABDUL KHADER

SAP# : 80019238

"S.A. INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY"

	ENGINEERING CORNER for INSPECTION		Doc. No.	ECIR- LFT - 105
			Rev. No	01
	CUSTOMER FEEDBACK FORM - LFT & ELEV		Rev. Date	1 NOV 2025
			Page No.	1 of 1

Issue Number : 02 & Issue Date : 03 FEB 2020

Feedback Form Number: 030367

Customer Details:

Client Name	SUDHAIR RENTALS	Contact Person Name	Arif shmshad
Client Address	ARAMCO PLANT OUTSIDE PARKING AREA, JUAYMAH	Department	2574279309
Email ID	logistics@sudhirrentals.com	Contact Number	0553503143
Inspection Date	09/12/2025	Inspector Name	ABDUL KHADER

Dear Sir/Madam,

We request you to kindly put a 'TICK' mark in the respective boxes against each aspect described below and to assess your feedback with respect to the service we have provided so far. Any other suggestion or remarks please indicate the same to improve further. Thank you for taking your time for giving your valuable feedback to us.

Description	Yes	No	Remarks
Did the Service provider Co. provide the right inspector with a valid qualification card?	☒		
Did the Service provider Co. respond for inspection within the expected time frame?	☒		
Was the inspector wearing the required personal protective equipment (PPE) during the inspection?	☒		
Did the inspection conducted safely and in accordance with Aramco's standards?	☒		
How satisfied are you with the overall service provided? * * * * *			
Would you consider using this Service Provider again for future inspections? * * * * *			
For any enquiry or concern, please contact: Inspection Dept. - ISSD Crane Inspection Unit (CIU)			

Any suggestions for improvement or additional services required?	Feedback given by (Customer Representative)
	