



REPORT OF A THOROUGH EXAMINATION

Issue Date: 16-Jun-2026

Certificate Number: ECI/SA/C-02804/26 Rev. No: 01	Report Number: 133218	Sticker Number: 110127
Date of Thorough Examination: 14-Jun-2026	Date of Expiration: 13-Dec-2026	S.O.#: 163 Ref.#: N/A

Client: SUDHIR EQUIPMENT RENTAL COMPANY	Address of Premises at Which the Examination Was Made: FADHLI
---	---

Description and Identification of the Equipment:	Load Test Detail	Safe Working Load(s)	Applied Load(s)
Equipment / Type : HEAVY EQUIPMENT / SKID LOADER Location of the Equipment : FADHLI Equipment ID No : SSKT-001 Equipment Serial No : B3ZA12038 Model : ST590 Manufacturer / Date of Manufacture : BOBCAT / 2018 Applied Standard : SASO-ISO-20474-3 - 2017 & BS EN 474-3 - 2022	N/A	0.3 m³	N/A

Examination after installation / In-Services		Was the Examination carried out Within an interval of					
☐ Initial ☒ Periodic Inspection ☐ Re-Inspection after Major Repair / Modification Or Overhaul		☐ 3 Months ☒ 6 Months ☐ 12 Months ☐ After the exceptional circumstances					
Additional Information about the equipment and Information / Description of the Parts / attachments with the equipment. N/A							
Description of the Load Test : N/A							
Pre Load Test NDT done by : N/A		% of Load Applied : N/A		Post Load Test NDT done by : N/A			
Result				PASS	☒	FAIL	
Is the above a defect which is of immediate danger to persons?				YES		NO	☒
Is the above a defect which is not yet but could become a danger to persons?				YES by :		NO	☒
Particulars of any repair, renewal or alteration required to remedy the defect identified above: N/A							
Is this equipment safe to operate?				YES	☒	NO	

Note: We thus attest that the aforementioned equipment has undergone a thorough Visual Inspection and /or Functional Test conducted by a qualified inspector in accordance with Engineering Corner for Inspection (E.C.I.) procedure / local / international standards.

Liability: The client or this assignee or supervisor in interest agrees to identify and hold harmless **Engineering corner for inspection Co.Ltd.** from and against any all claims, demands, lawsuits or actions for damages including legal fees to persons and/or property tangible, intangible or otherwise which may be against, **Engineering corner for inspection Co.Ltd.** incidental to, arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of **Engineering corner for inspection Co.Ltd.** its directors, others, employees or sub-contractors.

Inspected by: A.Muhammad Raseen Signature:	Approved & Reviewed By: NAJUMUDEEN 	QR Code:
---	--	--------------



Engineering Corner for Inspection Company Limited

INSPECTION CHECKLIST

Loaders

Doc. No.	ECIR - LFT - 30
Rev. No.	03
Rev. Date	17-FEB-2026
Page No.	2 of 5

Issue Number : 02 & Issue Date : 03-FEB-2020

Equipment Owner	SUDHIR EQUIPMENT RENTAL COMPANY /	Report No. & Date	133218 14-Jun-2026
Manufacturer / Year	BOBCAT / 2018	Location	FADHLI
Type / Model	HEAVY EQUIPMENT / SKID LOADER / ST590	Equipment ID. No.	SSKT-001
Inspection Date	14-Jun-2026	Equipment Sr. No.	B3ZA12038
Inspector Name	A.Muhammad Raseen	Capacity / SWL	0.3 m³
Standard	BE EN 474-1-2022, BS EN 474-3-2022, SASO ISO 20474-1-2017 & SASO ISO 20474-3-2017	Expiration Date	13-Dec-2026

Item No	ITEM NAME	PASS	FAIL	N/A	Item No	ITEM NAME	PASS	FAIL	N/A
GENERAL REQUIREMENTS & DOCUMENTATION					5.3	Hydraulic reservoir fluid level is correct and fluid is clean	☒		
1.1	Operator's manual and machine documentation available in appropriate language	☒			5.4	Lift and tilt cylinder anchor points and pins are secure and not worn	☒		
1.2	Previous inspection reports are checked and reviewed	☒			5.5	Cylinder rods show no significant scoring, pitting, or leakage	☒		
1.3	Machine identification plate legible and secure (serial no., weight, year of manufacture)	☒			5.6	Check Valve / Holding Valves for loader arms are functional (no drift)	☒		
1.4	Operator is trained and authorized for the specific equipment type	☒			LOADER ARM, LINKAGE & BUCKET				
1.5	Fire extinguisher is in place, accessible, and properly charged	☒			6.1	Loader arms, lift cylinders, and linkage show no cracks, bends, or unauthorized welds	☒		
1.6	Safety signs and decals are present, legible and not damaged	☒			6.2	Pivot pins, bushings, and retainers are secure and show no excessive wear	☒		
1.7	Rated capacity / load chart is displayed and legible	☒			6.3	Bucket and cutting edge are in serviceable condition	☒		
OPERATOR'S STATION (ROPS/FOPS CAB)					6.4	Bucket teeth (if equipped) are secure and not missing or excessively worn			☒
2.1	ROPS/FOPS structure certification plate present and structure intact	☒			6.5	Quick coupler (if equipped) is functional, locked, and safety device engaged			☒
2.2	Seat belt with warning device is fitted and in good condition			☒	6.6	Bucket level indicator is functional and visible to operator			☒
2.3	All control levers and pedals are clearly marked and function smoothly	☒			6.7	Lift arm stops are present and functional	☒		
2.4	Forward/reverse direction and gear selection controls function correctly	☒			TIRES / UNDERCARRIAGE & GENERAL STRUCTURE				
2.5	Audible warning device (horn) is operational	☒			7.1	All tires are serviceable, with correct pressure and no excessive wear/damage	☒		
2.6	All gauges and warning indicators are functional	☒			7.2	Wheel nuts are present, engaged properly, and torqued	☒		
2.7	Windows and mirrors are clean, secure and not damaged	☒			7.3	Rims are not damaged, cracked or rusted through	☒		
2.8	Wipers and washers are operational for adequate visibility			☒	7.4	Chassis and main frame show no cracks or damage	☒		
2.9	Entry/exit steps and handholds are secure and skid-resistant	☒			7.5	Guards for rotating parts (fan, belts, driveline) are in place and secure	☒		
2.10	Parking brake engagement warning indicator is functional	☒			7.6	Fuel tank, hydraulic tank supports, and straps are secure	☒		
2.11	Operator's seat adjustments are functional and seat is secured	☒			7.7	Underside of chassis shows no obvious faults, leaks, or damage	☒		
SAFETY DEVICES & CONTROLS					7.8	Axle mounting bolts are secure	☒		
3.1	Engine emergency stop device is functional and clearly identified			☒	7.9	Drive shaft bolts and universal joints are secure and not worn	☒		
3.2	Backup alarm is operational and audible	☒			7.10	Articulation joint and pins show no excessive wear or play	☒		
3.3	Loader lifting arm support device is present and functional	☒			LIGHTING & ELECTRICAL SYSTEM				
3.4	Control levers return to neutral when released	☒			8.1	Headlights, taillights, and work lights are operational	☒		
3.5	Seat-activated start/operation interlock is functional (if equipped)	☒			8.2	Turning signals and indicators are working correctly	☒		
POWERTRAIN, BRAKES & STEERING					8.3	Brake lights are operational	☒		
4.1	Engine shows no major leaks (oil, fuel, coolant)	☒			8.4	Beacon/warning light is operational (if equipped)	☒		
4.2	Service brakes are operational and effective	☒			8.5	Battery is secure, terminals are clean, and cover is in place	☒		
4.3	Parking brake holds the machine securely on maximum incline	☒			8.6	Wiring is secure with no exposed or damaged insulation	☒		
4.4	Steering system is responsive with no excessive play or leaks	☒			OPERATIONAL CHECKS (With Engine Running)				
4.5	Transmission shows no unusual noises, slipping or overheating	☒			9.1	No unusual engine, transmission, or hydraulic noises during operation	☒		
4.6	Drive axles and final drives show no leaks or damage	☒			9.2	Loader arm lift, lower, and float functions operate smoothly	☒		

	Engineering Corner for Inspection Company Limited INSPECTION CHECKLIST Loaders	Doc. No.	ECIR - LFT - 30
		Rev. No.	03
		Rev. Date	17-FEB-2026
		Page No.	3 of 5

Issue Number : 02 & Issue Date : 03-FEB-2020

Equipment Owner	SUDHIR EQUIPMENT RENTAL COMPANY /	Report No. & Date	133218 14-Jun-2026
Manufacturer / Year	BOBCAT / 2018	Location	FADHLI
Type / Model	HEAVY EQUIPMENT / SKID LOADER / ST590	Equipment ID. No.	SSKT-001
Inspection Date	14-Jun-2026	Equipment Sr. No.	B3ZA12038
Inspector Name	A.Muhammad Raseen	Capacity / SWL	0.3 m³
Standard	BE EN 474-1-2022, BS EN 474-3-2022, SASO ISO 20474-1-2017 & SASO ISO 20474-3-2017	Expiration Date	13-Dec-2026


Item No	ITEM NAME	PASS	FAIL	N/A	Item No	ITEM NAME	PASS	FAIL	N/A
4.7	Engine and transmission mounting bolts are secure	☒	☐	☐	9.3	Bucket tilt, dump, and rollback functions operate smoothly	☒	☐	☐
4.8	Radiator and cooling system show no leaks	☒	☐	☐	9.4	Machine travels forward and reverse in all ranges without issue	☒	☐	☐
HYDRAULIC SYSTEM					9.5	Steering functions correctly in both directions under load	☒	☐	☐
5.1	Hydraulic tanks, hoses, and lines show no leaks or damage	☒	☐	☐	9.6	No excessive drift or creep in loader arms or bucket when raised	☒	☐	☐
5.2	Hydraulic hose fittings and supports are secure	☒	☐	☐	9.7	Braking performance is adequate in both service and parking brakes	☒	☐	☐

Overall Comments

Inspected By : A.Muhammad Raseen	Customer Representative : ARIF
---	---------------------------------------



Certificate Number: ECI/SA/C-02804/26





شركة ركن الهندسة للفحص والمعاينة المحدودة
ENGINEERING CORNER FOR INSPECTION CO. LTD.



ENGINEERING CORNER FOR
INSPECTION CO. LTD. (ECI)



ECI. 110127

Capacity : 0.3 m³

Equipment No. : SSKT-001

Serial No. : B3ZA12038

Inspected Date : 14-Jun-2026

Next Inspection : 13-Dec-2026

Inspector : A.Muhammad Raseen

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894

E-mail Address:eci@eccgroupksa.com