



THIRD PARTY INSPECTION CERTIFICATE

MANLIFT

Certificate No : HIT-CRT-23-2620

Job No JO-INS-23-1436

Sticker No	2327
Result	Pass

Timesheet	CL-3909
Checklist	CL-3909

Client Name & Address	Inspection Date	29-Mar-2023
Sudhir Equipment Rental Company	Expiration Date	28-Sep-2023
Yanbu	Validity	6 Month's
Kingdom of Saudi Arabia	Types of Inspection	
Equipment Location	Yanbu	Periodic Visual & Functional

Equipment Description	Load Test Chart			
Telescopic Boom Lift (Manlift) with single basket, Double operative control system, Diesel driven hydraulic.	Boom ↔	Radius →	Test Load	S.W.L.
	(Meter)	(Meter)	(Tonne)	(Tonne)
	NA	NA	NA	NA

Load Limit (S.W.L.)	227 kg
Serial No.	300001989
Model	860 SJ
Horizontal Outreach	22.86 m
Working Height	28.21 m
Wire Rope Dia	Main: NA Aux: NA
Boom Length	NA
Wheel Type	Tyre

Manufacturer	JLG
Date of Mfg.	2019
Owner ID/Plat No	S28SJ-417
Max Platform Height	26.21 m
Machine Height	3.05 m
Machine Weight	16732 kg
Angle of Span	NA
Person Allowed	1

Previous Inspection Details	Next Inspection Date	Reference Standard
NA	29-Sep-23	ASME A 90.1

Recommendation

Found satisfactory at the time of Inspection.

Authorized By: ASHADULLAH KHAN

Inspected By: WAQAR AHMAD



Signature & Stamp

No liabilities will be considered against Haykalah Inspection Est. for failure, damage or other occurrence to client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance. The concerned inspector or representative has thoroughly examined the equipment in accordance to the relevant standards. Inspection indicates that the mentioned equipment/tools/machine has no apparent defects which may prove dangerous during normal operation and it's found satisfactory for further use with provided their regular maintenance and operated by a certified operator. This certificate/report shall not be generated without an official approval in between Haykalah Inspection Est. and Client. Certificate becomes invalid if any modification/repair is made to the equipment.

