



BV No. 0107614

Above Equipment was inspected by Bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

RECEIVER NAME: A BGD SIGNATURE: [Signature] INSPECTOR NAME: M. M. M.
BADGE#: _____ TELEPHONE No.: _____ TELEPHONE No.: 18000

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency