



Previous Sticker
No. 21-9611 Issued By BV

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	Road Pallet Fork	Oct 10, 2023		15130	No. 21-9611 Issued By BV
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
Suohor	S38JTP-467	MYDP		☒ Pass ☐ Fail	BV-21-9711
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
JLG	1200SOP	5000LBS	MEWP	0300235512	APRIL 09, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's ,ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Periodic inspection and function test for Boiler Superheaters (elevated) were not performed as per AS Solved CEF 034 R5592.5 - 4 Pass	

RECEIVER NAME: ARSL SIGNATURE: [Signature] INSPECTOR NAME: M. J. Jones
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 802 19106