



**BUREAU  
VERITAS**

**BV No. 0105202**

|                                                |                                        |                                     |                                        |                                                                                            |                                                  |
|------------------------------------------------|----------------------------------------|-------------------------------------|----------------------------------------|--------------------------------------------------------------------------------------------|--------------------------------------------------|
| <b>LIFTING EQUIPMENT<br/>INSPECTION REPORT</b> |                                        | Area<br><b>DAMMAN</b>               | Inspection Date<br><b>SEP 01, 2022</b> | Inspection Time<br><b>10:30</b>                                                            | Previous Sticker<br>No. <b>Initial</b> Issued By |
| Department / Contractor<br><b>SUDHIR</b>       | Equipment Number<br><b>SGIHESL-571</b> | Equipment Location<br><b>DAMMAN</b> |                                        | Equipment Result<br><input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail | New Sticker No.<br><b>BV-21-5616</b>             |
| Manufacturer<br><b>GENIE</b>                   | Model<br><b>GS-4046</b>                | Capacity<br><b>3500KG</b>           | Type<br><b>MEWP</b>                    | Equipment Serial Number<br><b>GS46D-20424</b>                                              | Sticker Expiration Date<br><b>FEB 28, 2023</b>   |

Above Equipment was inspected by Bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

| No. | DEFECIENCIES                             | CORRECTIVE ACTION TAKEN |
|-----|------------------------------------------|-------------------------|
|     | Initial inspection and function test for |                         |
|     | SELF PROPELLED Elevating work platform   |                         |
|     | AS per AS S.ARAMCO GJ 7.0 3rd. AMS 92.6. |                         |
|     | PASS                                     |                         |
|     |                                          |                         |
|     |                                          |                         |
|     |                                          |                         |
|     |                                          |                         |
|     |                                          |                         |
|     |                                          |                         |
|     |                                          |                         |
|     |                                          |                         |
|     |                                          |                         |

|                                |                                   |                                    |
|--------------------------------|-----------------------------------|------------------------------------|
| RECEIVER NAME: <b>THAISGER</b> | SIGNATURE:                        | INSPECTOR NAME: <b>M. Alkhalaf</b> |
| BADGE#: <b>8031</b>            | TELEPHONE No.: <b>055 2228231</b> | TELEPHONE No.: <b>1800000</b>      |

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency