



BV No. 236621

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]

RECEIVER NAME: THALSEER SIGNATURE: [Signature] INSPECTOR NAME: KEITH / 0001791

BADGE#: _____ TELEPHONE NO.: 055 222803/ TELEPHONE NO.: 0550486094