

The ICE Break-in Conundrum: Advanced Cylinder Topography, Synthetic Chemistry, and Thermal Cycling for Optimal Engine Break-In

Author:

Nathan Jarvis - MEng Student (Open University)

Review Article

Target Scope:

High-Performance / Powered Internal Combustion Engines (ICE)

August 2026

Table of Contents

Abstract	2
Introduction	3
Literature Review	4
1.1 Surface Mechanics and Topography Evolution	4
1.1.1 <i>The Initial Surface Topography</i>	4
1.1.2 <i>Microscopic Peak Shearing</i>	5
1.2 Synthetic Lubricants and Anti-Wear Chemistry	6
1.2.1 <i>The Synthetic Oil Paradox</i>	6
1.2.2 <i>ZDDP anti-wear chemistry</i>	6
1.3 Transient Dynamics, BMEP, and Cruise Control Mechanics	8
1.3.1 <i>Transient Dynamics and Thermal Expansion</i>	8
1.3.2 <i>BMEP (Brake Mean Effective Pressure) and Gas-Backed Ring Loading</i>	9
1.3.3 <i>Cruise Control, Idling, and Engine Braking</i>	10
1.4 Thermal Cycling and Structural Distortion	11
Findings and Conclusion	12

Abstract

High-performance internal combustion engines still require a strict 1,200-mile break-in period despite modern manufacturing advancements that achieve sub-millimetre tolerances. End-users and hobbyists often dismiss this requirement as an outdated protocol, largely due to a lack of technical awareness regarding the underlying tribological mechanisms. This is a review of how microscopic surface honing, synthetic oil chemistry, dynamic load in conjunction with speed variations, and thermal expansion make the break-in period essential for ensuring long-term component longevity. Furthermore, this review highlights why varying engine speed and Brake Mean Effective Pressure (BMEP) is critical for proper piston ring seating, while detailing the detrimental effects of static cruise control operation during early engine life.

Introduction

It is widely recognised that manufacturing processes and tolerances have come a long way in technological advancements for speed and precision. This has been made possible by ongoing investment and research, specifically within the automotive sector, into high-precision CNC machining and computer-controlled honing with sub-micron measuring tools. However, despite these advancements, modern high-performance engines still require a strict 1,200-mile break-in period with specific limitations on how to properly run in the engine and its individual critical components. A few examples of these mandates include restricting the vehicle from exceeding 100 mph, varying engine load and speed (RPM), and critically, avoiding long-distance cruise control use.

The majority of car owners and hobbyists typically believe this is an outdated practice and tend to ignore the strict procedures set out by automotive manufacturers. However, these practices still exist for multiple reasons. Although CNC machining allows manufacturers to machine at macro-level accuracy, microscopic surface-level peaks still exist on newly honed cylinder walls. It is essential these peaks are worn down to protect the oil-retaining valleys and ensure the piston rings seat correctly. Another reason is that under real operating temperatures and pressures, tribofilms and Anti-Wear Additives, such as ZDDP (Zinc Dialkyldithiophosphate), form to provide a nano-scale protective barrier that cushions surface peaks and prevents catastrophic scoring or welding.

The main aim and scope of this review is to resolve the engine break-in paradox by combining and synthesising tribological literature across four core focus points:

1. Surface Mechanics and Topography Evolution
2. Synthetic Lubricants and Anti-Wear Chemistry
3. Transient Dynamics, BMEP, and Cruise Control Mechanics
4. Thermal Cycling and Structural Distortion

Literature Review

1.1 Surface Mechanics and Topography Evolution

1.1.1 The Initial Surface Topography

Newly honed cylinders leave the manufacturing plant with a cross-hatch pattern and smooth plateaus on top. However, although this multi-step machining process does the majority of the heavy lifting, microscopic micro-asperities (S_{pk}) are still present [3]. To understand this surface structure, it is important to examine why both honing passes are carried out in a specific sequence.

First, coarse honing takes place. The honing tool cuts a series of deep diagonal channels that intersect each other at precise angles, typically between 30° and 45° , to establish the fundamental cross-hatch geometry [5]. This creates the cross-hatch pattern visible on the cylinder walls. These grooves act as microscopic oil reservoirs, keeping lubricant on the cylinder wall and preventing the piston rings from making direct metal-to-metal contact or welding to the liner.

Next, plateau honing is carried out as a finishing pass. The main aim of this second pass is to provide the piston rings with a smooth, stable sliding surface right out of the factory. This reduces initial scuffing while maintaining valley depth, leaving only residual micro-peaks (S_{pk}) to be gradually worn down during initial operation [3].




Figure 1.1: Microscopic view of plateau honed cylinder [6]

1.1.2 Microscopic Peak Shearing

During the first few hours of operation, the sliding motion of the piston rings makes contact with the tips of the tiny microscopic peaks (S_{pk}) on the cylinder. This motion exerts localised pressure onto the micro-peaks, causing them to rapidly shear off and wear down into smooth, flat plateaus. It is essential that only the peaks are worn down while the oil valleys and channels below are not affected. While S_{pk} rapidly shears off, S_{vk} (the deep cross-hatch grooves) remains almost untouched, ensuring oil can be held within these valleys to keep the piston rings lubricated for smooth gliding along the cylinder walls [5, 3]. However, if an engine is run at idle or consistently put under light load, cylinder glazing can occur. Cylinder glazing happens when engine oil bakes over the high-temperature micro-peaks, forming a hard, glossy lacquer. This stops the piston ring from ever seating correctly, meaning a complete engine teardown and re-honing of the cylinder is required.




Figure 1.2: Surface profile evolution showing peak reduction (S_{pk}) while maintaining valley depth (S_{vk}) adapted to ISO 13565-2 / ISO 25178 parameters [2].

Once the peaks have flattened out into smooth plateaus, the contact area between the piston ring and the cylinder wall becomes even. As demonstrated by Grabon et al. (2018), this reduces friction by around 30 to 40 percent and allows the piston ring to seat correctly against the cylinder wall [3]. If these peaks are not worn down completely, they do not allow the piston ring to fully expand outward and create a near-hermetic seal during the expansion stroke, causing blow-by. Blow-by reduces Brake Mean Effective Pressure (BMEP) and overall power output from the individual cylinder, while also introducing potential contaminants into the engine oil.

1.2 Synthetic Lubricants and Anti-Wear Chemistry

1.2.1 The Synthetic Oil Paradox

Synthetic oils used in modern engines are designed to stop metal-to-metal contact at all costs. However, this directly conflicts with the initial break-in process and can actually do more harm than good, risking the long-term life of the engine. As discussed in Section 1.1, piston rings need a controlled level of metal-to-metal contact so they can wear down those residual micro-peaks (S_{pk}). The very features that make synthetic oil so good for a high-mileage engine stop the piston rings from doing this job during break-in.

Under high pressure and aggressive sliding against the cylinder liner, high-film-strength synthetic oil creates a persistent hydrodynamic layer. As modelled by Chu et al. (2020), this dynamic fluid film prevents the piston ring from breaking through to deform and wear down the micro-peaks (S_{pk}) under boundary contact [1].

On top of this, modern synthetics are packed with friction modifiers like MoDTC (molybdenum dithiocarbamate) and organic friction modifiers (OFMs) like GMO (glycerol mono-oleate). These additives coat the liner surface to create a slippery nanolayer that drops boundary friction too low. This stops the piston rings from generating enough friction force to shear off or deform those micro-peaks, leaving the rings unseated.

1.2.2 ZDDP anti-wear chemistry

ZDDP (Zinc Dialkyldithiophosphate) is an anti-wear additive added to engine oils to protect components made from alloys such as iron and steel. It does not protect components simply by floating in the liquid oil; instead, it is activated by high mechanical contact pressure and surface heat, typically in the range of 80°C to 100°C [10].

When local pressure and heat within the cylinder reach the required threshold, ZDDP breaks down and reacts directly with the iron in the cylinder liner. It forms a microscopic, glass-like sacrificial coating that is only a few nanometres thick, known as a polyphosphate tribofilm [10]. This protective cushion allows the micro-peaks to shear down without causing catastrophic metal-to-metal welding or gouging.

If an engine is driven too lightly, idled excessively, or kept at low RPM during the break-in period, the pressure forcing the piston ring outward against the cylinder liner remains too low, and cylinder wall temperatures never reach the thermal threshold required for ZDDP to activate. Consequently, the ZDDP remains inert within the oil, leaving the cylinder liner vulnerable to anti-wear starvation. When the driver eventually puts the engine under higher load, forcing sudden higher pressures and temperatures, the rings (which are still not fully seated) hit the bare metal cylinder liner without a protective tribofilm, causing severe scoring and scuffing.

1.3 Transient Dynamics, BMEP, and Cruise Control Mechanics

1.3.1 Transient Dynamics and Thermal Expansion

Piston ring seating relies heavily on the engine being run up to full operating temperature and then cooled back down to a cold dormant state. This process is called thermal cycling and is essential during the break-in period. The two primary metals used within the engine's combustion section are cast iron (for the cylinder liner) and aluminium (for the piston). These two alloys warm up at different rates, with iron taking roughly twice as long as aluminium to reach full operating temperature. Furthermore, aluminium expands nearly twice as fast as iron under heat, meaning the physical clearance between the piston and cylinder liner temporarily shrinks during transient warm-up.

The cylinder liner and engine block are directly liquid-cooled, which draws heat away and forces the block to warm up more gradually, preventing thermal shock and structural stress fractures. In contrast, the aluminium piston crown comes into direct contact with combustion flames exceeding 1000°C , causing it to reach elevated temperatures within seconds to minutes [8].

When new engine components leave the factory machining process, they contain residual internal stresses. Heating these parts to operating temperature under controlled conditions and allowing them to cool back down to ambient temperature acts as a stress-relief process, letting the metal structure relax. Additionally, a cylinder liner is never a perfect cylinder; as it heats up, it distorts and warps slightly into its operational shape. It is therefore essential that the piston rings operate across the full thermal spectrum, from cold start and transient warm-up to full operating temperature and cool-down, so the rings conform correctly to the cylinder wall across all thermal states [8].




Figure 1.3: 3D profile representation of cylinder bore thermal distortion and out-of-roundness under operating temperatures [7].

1.3.2 BMEP (Brake Mean Effective Pressure) and Gas-Backed Ring Loading

Brake Mean Effective Pressure (BMEP) is simply a measure of the average pressure pushed down on top of the piston during the power stroke. It correlates directly with engine load; higher engine load creates high BMEP, while light load or idling results in low BMEP. If BMEP is too low, there is minimal pressure inside the cylinder, which stops the piston rings from pushing hard enough against the liner to seat in properly.

Piston rings have built-in spring tension to help them push outward against the cylinder wall, but this tension alone is insufficient to create a tight hermetic seal or shear down the surface micro-peaks (S_{pk}) during break-in. Instead, the rings rely on high pressure from combustion getting into the ring groove behind the ring itself, forcing it outward against the cylinder lining, a process called gas-backed ring loading [8, 9].

As gas-backed ring loading forces the piston rings outward against the cylinder liner, it physically shears off the surface micro-peaks (S_{pk}). This increased level of contact force creates localised friction points, exponentially increasing heat, right at those individual micro-peaks. This generates the ideal conditions for ZDDP activation, forming the protective anti-wear tribofilm directly where the micro-peaks were sheared. As a result, the newly exposed metal of the cylinder liner is immediately protected against friction and scuffing [8, 9].

1.3.3 Cruise Control, Idling, and Engine Braking

When travelling at a consistent speed or steady RPM, such as using cruise control, the piston rings travel over the exact same localised path thousands of times per minute. Under these steady conditions, BMEP remains low, producing minimal cylinder pressure. This prevents the piston rings from loading firmly against the cylinder wall, causing them to float on the oil film rather than shearing down the surface micro-peaks (S_{pk}). Furthermore, operating at low load or excessive idling causes unburned fuel and oil to bake onto the hot cylinder wall, creating a hard lacquer known as cylinder glazing, which permanently seals the crucial oil valleys and channels before ring seating can complete [8, 9].

Additionally, alternating between engine load and overrun changes the pressure acting on the piston rings. When decelerating in gear with the throttle closed, cylinder pressure drops, allowing the rings to relax against the cylinder wall. This change in contact pressure helps replenish the oil film around the upper ring pack and cools the contact surfaces, preventing localised hot spots and micro-scuffing.

While cyclic pressure variations replenish the oil film and allow suspended microscopic wear debris to be transported into the sump, these metallic particles remain circulating within the lubrication circuit. Without high-efficiency filtration, these microscopic contaminants risk entering critical oil channels and galleries, potentially causing restriction or oil starvation. This highlights the direct necessity of high oil filter performance during initial break-in and supports the manufacturer recommendations for early filter replacement during the initial run-in service [9].

1.4 Thermal Cycling and Structural Distortion

Due to localised heat spots caused naturally by engine operation, the engine block does not warm up evenly. The exhaust side of the block and cylinder liner operates on average between 100°C and 110°C hotter than the intake side, partially because the intake side is constantly cooled by incoming air and fuel, whereas the exhaust side is responsible for expelling hot combustion gases. Uneven heating also occurs vertically; the top deck where combustion takes place experiences extreme thermal loads, whereas the lower crankcase region stays significantly cooler. Because hot metal expands more than cooler metal, these thermal gradients cause macro-distortion, twisting the cylinder bore out of round. Although this macro-distortion is invisible to the naked eye, it directly alters the physical tolerances between the piston rings and cylinder wall, as illustrated by the asymmetrical thermal deformation contour in Figure 1.4 [4].




Figure 1.4: 3D cylinder liner deformation and thermal contour plot [4].

Newly machined and cast engine components retain internal residual stresses from manufacturing. Repeatedly heating these components to operating temperature and allowing them to cool back to ambient temperature acts as a thermal stress-relief process over time. As these stresses leave the metallurgy, the thermal warping of the engine block and cylinder liner stabilises into its final operational shape. Throughout this stabilisation process, the piston rings must constantly flex dynamically against the changing liner shape to maintain contact. Once the block stabilises, a properly seated piston ring ensures a complete hermetic seal, preventing fuel blow-by and oil contamination across all operating temperatures [8, 7].

Findings and Conclusion

Tribological Mechanism

The ultimate goal of the tribological mechanisms during the engine break-in period is to achieve full ring-to-bore seating without causing scuffing or premature wear to either the piston ring or the cylinder liner. As explored throughout this review, high mechanical contact force, driven by elevated BMEP and gas-backed ring loading, is required to ensure that reduced peak heights (S_{pk}) left after manufacturing are physically sheared down, creating a smooth surface profile while preserving deep oil-retention valleys (S_{vk}). In addition, ZDDP activation is required to provide a sacrificial anti-wear layer that protects the liner from scuffing, which could otherwise damage the oil channels and lead to oil starvation. For protective ZDDP tribofilms to activate, extreme localised flash temperatures and high contact shear stress are required. As soon as a micro-peak (S_{pk}) is sheared off, the ideal conditions for ZDDP activation are established, ensuring that newly exposed metal is protected immediately and reducing the risk of premature damage [8, 9].

Operational Reality

Unknown to the general customer, prolonged idling and using cruise control early in an engine's life, specifically during the break-in period, can hinder the piston rings from fully seating, leading to blow-by and oil contamination from unburnt fuel. Varying engine load and RPM prevents cylinder glazing from occurring before micro-peaks are sheared down to the target honed height. Utilising engine braking relieves the continuous mechanical load on the ring pack, allowing lubricant film replenishment and localised thermal dissipation at the ring–liner interface. Due to this debris generation, an initial run-in service is critical to inspect and replace the engine oil and oil filter, ensuring suspended particles do not re-enter the oil galleries and clog crucial oil-retention channels. Furthermore, ring seating requires multiple thermal cycles, ranging from ambient temperature up to full operating temperature and back to ambient, to ensure internal residual stresses are fully released and any structural warping of the block is stabilised [8, 9, 7].

Real-World Value

In conclusion, engine break-in is not an outdated concept or a myth created as a money-making scheme for customers. This review has demonstrated there are multiple vital physical reasons for adhering to a regimented break-in period. We have covered areas regarding surface topography and engineering, chemistry and tribological films, dynamic loading of the engine to ensure adequate pressure within the cylinder environment, and lastly, thermal stabilisation of the cylinder and engine block due to residual manufacturing stresses and thermal macro-distortion.

When an engine is run in correctly and properly maintained, including undergoing an early break-in service if recommended by the manufacturer, it ensures the engine operates at peak performance without requiring excessive maintenance. Long-term reliability is significantly improved because blow-by is minimised and oil contamination from unburnt fuel is prevented. This also results in direct cost savings for the consumer through reduced oil consumption over the lifespan of the vehicle.

Overall, this review has demonstrated that a break-in period remains essential. Although modern manufacturing processes allow for sub-micron tolerances to be achieved, real-world operating environments and thermomechanical situations cannot be fully replicated during factory production.

Bibliography

- [1] N. R. Chu et al. “A Mixed Lubrication Model of Piston Rings on Cylinder Liner Contacts Considering Temperature-Dependent Shear Thinning and Elastic–Plastic Contact”. In: *ASME Journal of Tribology* 142.5 (2020), p. 051601. DOI: 10.1115/1.4045573.
- [2] *Geometrical Product Specifications (GPS) — Surface Texture: Profile Method; Surfaces Having Stratified Functional Properties—Part 2: Height Characterization Using the Linear Material Ratio Curve*. Geneva, Switzerland: International Organization for Standardization, 1996.
- [3] Wieslaw Grabon et al. “Evolutions of Cylinder Liner Surface Texture and Tribological Performance of Piston Ring-Liner Assembly”. In: *Tribology International* 127 (2018), pp. 442–456. DOI: 10.1016/j.triboint.2018.06.028.
- [4] Haining He et al. “Dynamic Deformation Testing and Analysis of Wet Cylinder Liners Using the Eddy Current Method”. In: *Energies* 18.16 (2025), p. 4421. DOI: 10.3390/en18164421.
- [5] Yang Hu et al. “Mutual Influence of Plateau Roughness and Groove Texture of Honed Surface on Frictional Performance of Piston Ring–Liner System”. In: *Proceedings of the Institution of Mechanical Engineers, Part J: Journal of Engineering Tribology* 231.10 (2017), pp. 1312–1325. DOI: 10.1177/1350650117697475.
- [6] S. Mezghani et al. “Energy Efficiency Optimization of Engine by Frictional Reduction of Functional Surfaces of Cylinder Ring–Pack System”. In: *Tribology International* 59 (2013), pp. 240–247. DOI: 10.1016/j.triboint.2012.01.015.
- [7] G. Offner, P. Knafl, and M. Aigner. “Advanced Simulation Methods for Cylinder Bore Distortion and Piston Ring Dynamic Interaction”. In: *SAE International Journal of Engines* 10.4 (2017), pp. 1820–1832. DOI: 10.4271/2017-01-0812.
- [8] M. Priest and C. M. Taylor. “Automobile Engine Tribology—Approaching the Surface”. In: *Wear* 241.2 (2000), pp. 193–203. DOI: 10.1016/S0043-1648(00)00375-6.
- [9] Edward W. Schneider et al. “Real-Time Engine Wear Measurement of Piston Ring Face and Cylinder Bore Using Thin-Layer Activation”. In: *SAE Technical Paper* 880252 (1988). DOI: 10.4271/880252.
- [10] Hugh Spikes. “The History and Mechanisms of ZDDP”. In: *Tribology Letters* 17.3 (2004), pp. 469–489. DOI: 10.1023/B:TRIL.0000044495.26882.b5.