Temperature and **Humidity Detector** Idle OFF ON shut off [!= battery] when [power out] / switch to battery power [= battery] mode after(10m) **PAUSE**









