Members in Attendance

- Josh Mendez (Sponsor/Advisor)
- Nathan Truong
- Felix Moss
- Annika Boyd
- Eisa Alsharifi

Agenda

- PCB soldering work
- Show box design updates
- MAX1032 updates

_

Notes

- Nathan has completed all through-hole components, just needs to complete SMD components
 - SMD cap components may be too small
 - 1206 caps are needed, will be replaced by annika on PCB
 - Josh helped nathan solder some of the other SMD components onto the full pcb
- Changed 10uF cap to 1uF on schematic
- PCB Mounting Hole is 4mm
 - Mounting holes are 4.3mm away from the edges of the PCB
- MAX1032 PCB was accidentally burnt by a heat gun, need to reprint and resolder
- Got a new ESP32 ucontroller for testing purposes
- Team blocked due to capacitor wait
- Possibly may use OLED screen that Felix used last term
- Planned out weekly meetings for next term, 12pm monday