

OBD-II Diagnostic Trouble Code Reference — Critical & High Severity

This reference covers 529 OBD-II diagnostic trouble codes classified as Critical or High severity, curated from the project's OBD knowledge base. Lower-severity codes are served directly through the structured OBD lookup API (Phase 5) rather than duplicated here; this document focuses on the codes most relevant to driver safety and trip-readiness decisions.

Prefix legend: P = Powertrain (engine/transmission), B = Body, C = Chassis, U = Network/Communication.

Body

B2105 — Throttle Position Input Out of Range Low [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

B2106 — Throttle Position Input Out of Range High [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

Chassis

C0049 — Brake Fluid Level [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

C004B — Brake Fluid Level Sensor/Switch Circuit/Open [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

C1125 — Brake Fluid Level Sensor Input Circuit Failure [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

C1187 — Brake Fluid Level Sensor Input Open Circuit [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

C1188 — Brake Fluid Level Sensor Input Short Circuit To Battery [Critical]

Symptoms: Electrical issues, Starting problems

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

C1189 — Brake Fluid Level Sensor Input Short Circuit To Ground [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

C1284 — Oil Pressure Switch Failure [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

C1781 — Engine Coolant Temperature Signal Missing/Fault [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

Cooling System

P00B1 — Radiator Coolant Temperature Sensor Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00B2 — Radiator Coolant Temperature Sensor Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00B3 — Radiator Coolant Temperature Sensor Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00B4 — Radiator Coolant Temperature Sensor Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00B5 — Radiator Coolant Temperature Sensor Circuit Intermittent/Erratic [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00B6 — Radiator Coolant Temperature/Engine Coolant Temperature Correlation [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0115 — Engine Coolant Temperature Circuit Malfunction [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0116 — Engine Coolant Temperature Circuit Range/Performance Problem [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0117 — Engine Coolant Temperature Circuit Low Input [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0119 — Engine Coolant Temperature Circuit Intermittent [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P011A — Engine Coolant Temperature Sensor 1/2 Correlation [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P012F — Engine Coolant Temperature / Engine Oil Temperature Correlation [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P01E3 — Engine Coolant Temperature Sensor 3 Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P01E4 — Engine Coolant Temperature Sensor 3 Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P01E5 — Engine Coolant Temperature Sensor 3 Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P01E6 — Engine Coolant Temperature Sensor 3 Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P01E7 — Engine Coolant Temperature Sensor 3 Circuit Intermittent/Erratic [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P01F0 — Coolant Temperature Relapsed Below Diagnostic Monitoring Temperature [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P050C — Cold Start Engine Coolant Temperature Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P060F — Internal Control Module Coolant Temperature Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P063F — Auto Configuration Engine Coolant Temperature Input Not Present [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0A00 — Motor Electronics Coolant Temperature Sensor A Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0A01 — Motor Electronics Coolant Temperature Sensor A Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0A02 — Motor Electronics Coolant Temperature Sensor A Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0A03 — Motor Electronics Coolant Temperature Sensor A Circuit High **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0A04 — Motor Electronics Coolant Temperature Sensor A Circuit Intermittent **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0C42 — Hybrid/EV Battery Pack Coolant Temperature Sensor A Circuit **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0C43 — Hybrid/EV Battery Pack Coolant Temperature Sensor A Circuit Range/Performance **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0C44 — Hybrid/EV Battery Pack Coolant Temperature Sensor A Circuit Low **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0C45 — Hybrid/EV Battery Pack Coolant Temperature Sensor A Circuit High **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0C46 — Hybrid/EV Battery Pack Coolant Temperature Sensor A Circuit Intermittent/Erratic [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CBC — Drive Motor A Coolant Temperature Sensor Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CBD — Drive Motor A Coolant Temperature Sensor Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CBE — Drive Motor A Coolant Temperature Sensor Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CBF — Drive Motor A Coolant Temperature Sensor Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CC0 — Drive Motor A Coolant Temperature Sensor Circuit Intermittent [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CD5 — Hybrid/EV Battery Pack Coolant Temperature Sensor B Circuit **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CD6 — Hybrid/EV Battery Pack Coolant Temperature Sensor B Circuit **Range/Performance [Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CD7 — Hybrid/EV Battery Pack Coolant Temperature Sensor B Circuit Low **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CD8 — Hybrid/EV Battery Pack Coolant Temperature Sensor B Circuit High **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CD9 — Hybrid/EV Battery Pack Coolant Temperature Sensor B Circuit **Intermittent/Erratic [Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CEE — Hybrid/EV Electronics Coolant Temperature Sensor A Circuit **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CEF — Hybrid/EV Electronics Coolant Temperature Sensor A Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CF0 — Hybrid/EV Electronics Coolant Temperature Sensor A Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CF1 — Hybrid/EV Electronics Coolant Temperature Sensor A Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0CF2 — Hybrid/EV Electronics Coolant Temperature Sensor A Circuit Intermittent/Erratic [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0E81 — Auxiliary Cooling System Coolant Temperature Sensor A Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0E82 — Auxiliary Cooling System Coolant Temperature Sensor A Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0E83 — Auxiliary Cooling System Coolant Temperature Sensor A Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0E84 — Auxiliary Cooling System Coolant Temperature Sensor A Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P1119 — Engine Coolant Temperature (ECT) Sensor Circuit Intermittent Low Voltage/IAT - B Circuit Low Input [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P1120 — Engine Coolant Temperature (ECT) Sensor Circuit Intermittent High Voltage/IAT - B Circuit High Input [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P1803 — Coolant Temperature Circuit Malfunction [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2182 — Engine Coolant Temperature Sensor 2 Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2183 — Engine Coolant Temperature Sensor 2 Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2184 — Engine Coolant Temperature Sensor 2 Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2185 — Engine Coolant Temperature Sensor 2 Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2186 — Engine Coolant Temperature Sensor 2 Circuit Intermittent/Erratic [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P25AF — Coolant Temperature Control Module Requested MIL Illumination [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2AFC — Engine Coolant Temperature Sensor 4 Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2AFD — Engine Coolant Temperature Sensor 4 Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2AFE — Engine Coolant Temperature Sensor 4 Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2AFF — Engine Coolant Temperature Sensor 4 Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B20 — Hybrid/EV Electronics Coolant Temperature Sensor B Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B21 — Hybrid/EV Electronics Coolant Temperature Sensor B Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B22 — Hybrid/EV Electronics Coolant Temperature Sensor B Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B23 — Hybrid/EV Electronics Coolant Temperature Sensor B Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B24 — Hybrid/EV Electronics Coolant Temperature Sensor C Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B25 — Hybrid/EV Electronics Coolant Temperature Sensor C Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B26 — Hybrid/EV Electronics Coolant Temperature Sensor C Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B27 — Hybrid/EV Electronics Coolant Temperature Sensor C Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B2B — Engine Coolant Temperature Sensor 5 Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B2C — Engine Coolant Temperature Sensor 5 Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B2D — Engine Coolant Temperature Sensor 5 Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2B2E — Engine Coolant Temperature Sensor 5 Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BB4 — Engine Coolant Temperature Sensor 4 Circuit Intermittent/Erratic [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BB5 — Engine Coolant Temperature Sensor 5 Circuit Intermittent/Erratic [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BB6 — Engine Coolant Temperature Sensor 6 Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BB7 — Engine Coolant Temperature Sensor 6 Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BB8 — Engine Coolant Temperature Sensor 6 Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BB9 — Engine Coolant Temperature Sensor 6 Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BBA — Engine Coolant Temperature Sensor 6 Circuit Intermittent/Erratic [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BD8 — Motor Electronics Coolant Temperature Sensor B Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BD9 — Motor Electronics Coolant Temperature Sensor B Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BDA — Motor Electronics Coolant Temperature Sensor B Circuit Low **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BDB — Motor Electronics Coolant Temperature Sensor B Circuit High **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BDC — Motor Electronics Coolant Temperature Sensor C Circuit **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BDD — Motor Electronics Coolant Temperature Sensor C Circuit **Range/Performance** **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BDE — Motor Electronics Coolant Temperature Sensor C Circuit Low **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2BDF — Motor Electronics Coolant Temperature Sensor C Circuit High **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2D2A — Hybrid/EV Electronics Coolant Temperature Sensor A/B Correlation **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2D2B — Hybrid/EV Battery Pack Coolant Temperature Sensor A/B Correlation **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2D2C — Engine Coolant Temperature Measurement System - Multiple Sensor Correlation **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2D52 — Hybrid/EV Battery Pack Coolant Temperature Sensor C Circuit **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2D53 — Hybrid/EV Battery Pack Coolant Temperature Sensor C Circuit Range/Performance **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2D54 — Hybrid/EV Battery Pack Coolant Temperature Sensor C Circuit Low **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2D55 — Hybrid/EV Battery Pack Coolant Temperature Sensor C Circuit High [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2D56 — Hybrid/EV Battery Pack Coolant Temperature Sensor C Circuit Intermittent/Erratic [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2E74 — Hybrid/EV Battery Pack Coolant Temperature Sensor D Circuit [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2E75 — Hybrid/EV Battery Pack Coolant Temperature Sensor D Circuit Range/Performance [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2E76 — Hybrid/EV Battery Pack Coolant Temperature Sensor D Circuit Low [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2E77 — Hybrid/EV Battery Pack Coolant Temperature Sensor D Circuit High [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2E78 — Hybrid/EV Battery Pack Coolant Temperature Sensor D Circuit Intermittent/Erratic [Critical]

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0118 — Engine Coolant Temperature Circuit High Input [High]

Symptoms: Temperature gauge high, Engine overheating, Steam from hood

Impact: Risk of engine overheating and severe damage

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34A4 — A Camshaft Position Actuator Temperature Sensor Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34A5 — A Camshaft Position Actuator Temperature Sensor Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34A6 — A Camshaft Position Actuator Temperature Sensor Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34A7 — A Camshaft Position Actuator Temperature Sensor Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34A8 — A Camshaft Position Actuator Temperature Sensor Circuit Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34A9 — A Camshaft Position Actuator Temperature Sensor Range/Performance Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34AA — A Camshaft Position Actuator Temperature Sensor Circuit Low Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34AB — A Camshaft Position Actuator Temperature Sensor Circuit High Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B4 — B Camshaft Position Actuator Temperature Sensor Circuit Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B5 — B Camshaft Position Actuator Temperature Sensor Range/Performance Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B6 — B Camshaft Position Actuator Temperature Sensor Circuit Low Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B7 — B Camshaft Position Actuator Temperature Sensor Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B8 — B Camshaft Position Actuator Temperature Sensor Circuit Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B9 — B Camshaft Position Actuator Temperature Sensor Range/Performance Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34BA — B Camshaft Position Actuator Temperature Sensor Circuit Low Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34BB — B Camshaft Position Actuator Temperature Sensor Circuit High Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C4 — A Camshaft Position Actuator Control Circuit Driver Current/Temperature Too High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C5 — A Camshaft Position Actuator Control Circuit Driver Current/Temperature Too High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C6 — B Camshaft Position Actuator Control Circuit Driver Current/Temperature Too High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C7 — B Camshaft Position Actuator Control Circuit Driver Current/Temperature Too High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

Electrical/Charging

P0523 — Engine Oil Pressure Sensor/Switch Circuit Low Voltage [Critical]

Symptoms: Electrical issues, Starting problems

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P0530 — Engine Oil Pressure Sensor/Switch Circuit High Voltage [Critical]

Symptoms: Electrical issues, Starting problems

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P0562 — System Voltage Low [High]

Symptoms: Electrical issues, Warning lights on, Starting problems

Impact: Risk of electrical system failure and no-start condition

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0563 — System Voltage High [High]

Symptoms: Electrical issues, Warning lights on, Starting problems

Impact: Risk of electrical system failure and no-start condition

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

Fuel & Emission

P008F — Engine Coolant Temperature/Fuel Temperature Correlation [Critical]

Symptoms: Poor fuel economy, Temperature gauge high, Rough idle, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00DE — Charge Air Cooler Coolant Temperature Sensor A Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00DF — Charge Air Cooler Coolant Temperature Sensor A Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00E0 — Charge Air Cooler Coolant Temperature Sensor A Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00E1 — Charge Air Cooler Coolant Temperature Sensor A Circuit High **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P00E2 — Charge Air Cooler Coolant Temperature Sensor A Intermittent/Erratic **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P011B — Engine Coolant Temperature/Intake Air Temperature Correlation **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P011E — Engine Coolant Temperature 1 / Ambient Air Temperature Correlation **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P011F — Engine Coolant Temperature 2 / Ambient Air Temperature Correlation **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0125 — Insufficient Coolant Temperature for Closed Loop Fuel Control; **[Critical]**

Symptoms: Poor fuel economy, Temperature gauge high, Rough idle, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0217 — Engine Coolant Over Temperature Condition [Critical]

Symptoms: Temperature gauge high, Engine overheating, Steam from hood

Impact: Severe risk of engine damage — immediate attention required

Recommendation: Stop driving immediately and seek emergency repair

P2AC7 — Charge Air Cooler Coolant Temperature Sensor B Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2AC8 — Charge Air Cooler Coolant Temperature Sensor B Circuit Range/Performance [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2AC9 — Charge Air Cooler Coolant Temperature Sensor B Circuit Low [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2ACA — Charge Air Cooler Coolant Temperature Sensor B Circuit High [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P2ACB — Charge Air Cooler Coolant Temperature Sensor B Intermittent/Erratic [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

P0087 — Fuel Rail/System Pressure Too Low [High]

Symptoms: Hard starting, Engine stalling, Poor performance

Impact: Engine starvation risk and potential no-start condition

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0088 — Fuel Rail/System Pressure Too High [High]

Symptoms: Hard starting, Engine stalling, Poor performance

Impact: Engine starvation risk and potential no-start condition

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0313 — Misfire Detected With Low Fuel [High]

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0363 — Misfire Detected - Fueling Disabled [High]

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1336 — Misfire Rate Catalyst Damage Fault - Bank 1 [High]

Symptoms: Engine shaking, Rotten egg smell, Loss of power, Rough idle, Failed emissions test

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1340 — Misfire Rate Catalyst Damage Fault - Bank 2 [High]

Symptoms: Engine shaking, Rotten egg smell, Loss of power, Rough idle, Failed emissions test

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2073 — Manifold Absolute Pressure/Mass Air Flow - Throttle Position Correlation at Idle [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2074 — Manifold Absolute Pressure/Mass Air Flow - Throttle Position Correlation at Higher Load [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25D0 — Exhaust Camshaft Actuator Park Lock Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25D1 — Exhaust Camshaft Actuator Park Lock Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25D2 — Exhaust Camshaft Actuator Park Lock Control Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25D3 — Exhaust Camshaft Actuator Park Lock Control Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25D4 — Exhaust Camshaft Actuator Park Lock Control Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25D5 — Exhaust Camshaft Actuator Park Lock Control Circuit High Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E58 — Alternative Fuel Random/Multiple Cylinder Misfire Detected **[High]**

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E59 — Cylinder 1 Alternative Fuel Misfire Detected **[High]**

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E5A — Cylinder 2 Alternative Fuel Misfire Detected **[High]**

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E5B — Cylinder 3 Alternative Fuel Misfire Detected **[High]**

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E5C — Cylinder 4 Alternative Fuel Misfire Detected **[High]**

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E5D — Cylinder 5 Alternative Fuel Misfire Detected **[High]**

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E5E — Cylinder 6 Alternative Fuel Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E5F — Cylinder 7 Alternative Fuel Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E60 — Cylinder 8 Alternative Fuel Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2E61 — Alternative Fuel Misfire Detected With Low Fuel [High]

Symptoms: Loss of power, Engine shaking, Rough idle, Poor fuel economy

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

Ignition System

P0011 — A Camshaft Position - Timing Over-Advanced or System Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0012 — A Camshaft Position - Timing Over-Retarded Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0014 — B Camshaft Position - Timing Over-Advanced or System Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0015 — B Camshaft Position - Timing Over-Retarded Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0021 — A Camshaft Position - Timing Over-Advanced or System Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0022 — A Camshaft Position - Timing Over-Retarded Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0024 — B Camshaft Position - Timing Over-Advanced or System Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0025 — B Camshaft Position - Timing Over-Retarded Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0301 — Cylinder 1 Misfire Detected [High]

Symptoms: Engine shaking, Rough idle, Loss of power, Increased fuel consumption

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0302 — Cylinder 2 Misfire Detected [High]

Symptoms: Engine shaking, Rough idle, Loss of power, Increased fuel consumption

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0303 — Cylinder 3 Misfire Detected [High]

Symptoms: Engine shaking, Rough idle, Loss of power, Increased fuel consumption

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0304 — Cylinder 4 Misfire Detected [High]

Symptoms: Engine shaking, Rough idle, Loss of power, Increased fuel consumption

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0305 — Cylinder 5 Misfire Detected [High]

Symptoms: Engine shaking, Rough idle, Loss of power, Increased fuel consumption

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0306 — Cylinder 6 Misfire Detected [High]

Symptoms: Engine shaking, Rough idle, Loss of power, Increased fuel consumption

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0307 — Cylinder 6 Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0308 — Cylinder 7 Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0309 — Cylinder 8 Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0310 — Cylinder 9 Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0311 — Cylinder 10 Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0312 — Cylinder 11 Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0314 — Single Cylinder Misfire (Cylinder not Specified) [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0316 — Engine Misfire Detected on Startup (First 1000 Revolutions) [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0320 — Cylinder 12 Misfire Detected [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0324 — Knock/Combustion Vibration Control System Error [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0326 — Knock Sensor 1 Circuit Malfunction (Bank 1 or Single Sensor) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0327 — Knock Sensor 1 Circuit Range/Performance (Bank 1 or Single Sensor) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0328 — Knock Sensor 1 Circuit Low Input (Bank 1 or Single Sensor) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0329 — Knock Sensor 1 Circuit High Input (Bank 1 or Single Sensor) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P032A — Knock/Combustion Vibration Sensor C Circuit [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P032B — Knock/Combustion Vibration Sensor C Circuit Range/Performance [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P032C — Knock/Combustion Vibration Sensor C Circuit Low [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P032D — Knock/Combustion Vibration Sensor C Circuit High [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P032E — Knock/Combustion Vibration Sensor C Circuit Intermittent [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0330 — Knock Sensor 1 Circuit Intermittent (Bank 1 or Single Sensor) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0331 — Knock Sensor 2 Circuit Malfunction (Bank 2) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0332 — Knock Sensor 2 Circuit Range/Performance (Bank 2) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0333 — Knock Sensor 2 Circuit Low Input (Bank 2) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0334 — Knock Sensor 2 Circuit High Input (Bank 2) [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0335 — Crankshaft Position Sensor A Circuit Malfunction [High]

Symptoms: Engine stalling, Hard to start, Engine misfires

Impact: Engine may not start or may stall at speed

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P033A — Knock/Combustion Vibration Sensor D Circuit [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P033B — Knock/Combustion Vibration Sensor D Circuit Range/Performance [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P033C — Knock/Combustion Vibration Sensor D Circuit Low [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P033D — Knock/Combustion Vibration Sensor D Circuit High [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P033E — Knock/Combustion Vibration Sensor D Circuit Intermittent [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0351 — Ignition Coil A Primary/Secondary Circuit Malfunction [High]

Symptoms: Engine misfire, Rough idle, Loss of power

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P052A — Cold Start A Camshaft Position Timing Over-Advanced Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P052B — Cold Start A Camshaft Position Timing Over-Retarded Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P052C — Cold Start A Camshaft Position Timing Over-Advanced Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P052D — Cold Start A Camshaft Position Timing Over-Retarded Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P054A — Cold Start B Camshaft Position Timing Over-Advanced Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P054B — Cold Start B Camshaft Position Timing Over-Retarded Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P054C — Cold Start B Camshaft Position Timing Over-Advanced Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P054D — Cold Start B Camshaft Position Timing Over-Retarded Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P05CC — Cold Start A Camshaft Position Timing Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P05CD — Cold Start A Camshaft Position Timing Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P05CE — Cold Start B Camshaft Position Timing Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P05CF — Cold Start B Camshaft Position Timing Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P06B6 — Internal Control Module Knock/Combustion Vibration Sensor Processor 1 Performance [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P06B7 — Internal Control Module Knock/Combustion Vibration Sensor Processor 2 Performance [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1317 — Misfire Monitor AICE Chip Fault [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1341 — Persistent Misfire [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1382 — Crankshaft Position (CKP)/Ignition Coil - Cylinder 4 - Early Activation Fault [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1385 — Misfire Detected - Rough Road Data Not Available [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1386 — Variable Cam Timing Overadvanced (Bank #1)/ Misfire Detected - No Communication with BCM [High]

Symptoms: Loss of power, Engine shaking, Rough idle

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2336 — Cylinder 1 Above Knock/Combustion Vibration Sensor Threshold [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2337 — Cylinder 2 Above Knock/Combustion Vibration Sensor Threshold [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2338 — Cylinder 3 Above Knock/Combustion Vibration Sensor Threshold [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2339 — Cylinder 4 Above Knock/Combustion Vibration Sensor Threshold [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2340 — Cylinder 5 Above Knock/Combustion Vibration Sensor Threshold [High]

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2341 — Cylinder 6 Above Knock/Combustion Vibration Sensor Threshold **[High]**

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2342 — Cylinder 7 Above Knock/Combustion Vibration Sensor Threshold **[High]**

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2343 — Cylinder 8 Above Knock/Combustion Vibration Sensor Threshold **[High]**

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2344 — Cylinder 9 Above Knock/Combustion Vibration Sensor Threshold **[High]**

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2345 — Cylinder 10 Above Knock/Combustion Vibration Sensor Threshold **[High]**

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2346 — Cylinder 11 Above Knock/Combustion Vibration Sensor Threshold **[High]**

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2347 — Cylinder 12 Above Knock/Combustion Vibration Sensor Threshold **[High]**

Symptoms: Engine knocking, Reduced performance

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

Network/Communication

U0116 — Lost Communication With Coolant Temperature Control Module **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U0456 — Invalid Data Received From Coolant Temperature Control Module **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U0600 — Lost Communication With Engine Oil Pressure Sensor A **[Critical]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

U0630 — Lost Communication With Engine Coolant Temperature Sensor 4 **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U0631 — Lost Communication With Engine Coolant Temperature Sensor 5 **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U0634 — Lost Communication With Hybrid/EV Battery Pack Coolant Temperature Sensor A **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U0635 — Lost Communication With Hybrid/EV Battery Pack Coolant Temperature Sensor B **[Critical]**

Symptoms: Electrical issues, Temperature gauge high, Engine overheating, Starting problems

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U0638 — Lost Communication With Hybrid/EV Electronics Coolant Temperature Sensor A **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U0639 — Lost Communication With Hybrid/EV Electronics Coolant Temperature Sensor B **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U063A — Lost Communication With Hybrid/EV Electronics Coolant Temperature Sensor C **[Critical]**

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U3570 — Stack Inlet Coolant Temperature Sensor Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U3571 — Stack Outlet Coolant Temperature Sensor 1 Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U3572 — Stack Outlet Coolant Temperature Sensor 2 Circuit [Critical]

Symptoms: Temperature gauge high, Engine overheating

Impact: Risk of engine overheating and severe damage

Recommendation: Stop driving immediately and seek emergency repair

U012E — Lost Communication With Camshaft Position Control Module [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

U042F — Invalid Data Received From Camshaft Position Control Module [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

U0688 — Lost Communication With Throttle Position Sensor/Switch G [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

Sensor/Circuit

P0218 — Transmission Over Temperature Condition [Critical]

Symptoms: Temperature gauge high, Engine overheating, Steam from hood

Impact: Severe risk of engine damage — immediate attention required

Recommendation: Stop driving immediately and seek emergency repair

P0521 — Engine Oil Pressure Sensor/Switch Circuit Malfunction [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P0522 — Engine Oil Pressure Sensor/Switch Circuit Range/Performance [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P0524 — Engine Oil Pressure Too Low [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P055A — Engine Oil Pressure Sensor/Switch B Circuit [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P055B — Engine Oil Pressure Sensor/Switch B Range/Performance [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P055C — Engine Oil Pressure Sensor/Switch B Low [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P055D — Engine Oil Pressure Sensor/Switch B High [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P055F — Engine Oil Pressure Out of Range [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P06DA — Engine Oil Pressure Control Circuit/Open [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P06DB — Engine Oil Pressure Control Circuit Low [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P06DC — Engine Oil Pressure Control Circuit High [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P06DD — Engine Oil Pressure Control Circuit Performance/Stuck Off [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P06DE — Engine Oil Pressure Control Circuit Stuck On [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P1694 — Oil Pressure Control Solenoid Circuit Malfunction [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P25AE — Piston Cooling Oil Pressure Too Low [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P2B57 — Low Engine Oil Pressure - Camshaft Control Disabled [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P2D8E — Engine Oil Pressure Sensor/Switch C Circuit [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P2D8F — Engine Oil Pressure Sensor/Switch C Circuit Low [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P2D90 — Engine Oil Pressure Sensor/Switch C Circuit High [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P2D91 — Engine Oil Pressure Sensor/Switch C Circuit Range/Performance [Critical]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

P000A — A Camshaft Position Slow Response Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P000B — B Camshaft Position Slow Response Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P000C — A Camshaft Position Slow Response Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P000D — B Camshaft Position Slow Response Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0010 — A Camshaft Position Actuator A Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0013 — B Camshaft Position Actuator A Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0016 — Crankshaft Position - Camshaft Position Correlation Bank 1 Sensor A [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0017 — Crankshaft Position - Camshaft Position Correlation Bank 1 Sensor B **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0018 — Crankshaft Position - Camshaft Position Correlation Bank 2 Sensor A **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0019 — Crankshaft Position - Camshaft Position Correlation Bank 2 Sensor B **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P001A — A Camshaft Profile Actuator A Control Circuit/Open Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P001B — A Camshaft Profile Actuator A Control Circuit Low Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P001C — A Camshaft Profile Actuator A Control Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P001D — A Camshaft Profile Actuator A Control Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P001E — A Camshaft Profile Actuator A Control Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P001F — A Camshaft Profile Actuator A Control Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0020 — A Camshaft Position Actuator A Control Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0023 — B Camshaft Position Actuator A Control Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P002A — B Camshaft Profile Actuator A Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P002B — B Camshaft Profile Actuator A Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P002C — B Camshaft Profile Actuator A Control Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P002D — B Camshaft Profile Actuator A Control Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P002E — B Camshaft Profile Actuator A Control Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P002F — B Camshaft Profile Actuator A Control Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P003C — A Camshaft Profile Actuator A Control Performance/Stuck Off Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P003D — A Camshaft Profile Actuator A Control Stuck On Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P003E — A Camshaft Profile Actuator A Control Performance/Stuck Off Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P003F — A Camshaft Profile Actuator A Control Stuck On Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P005A — B Camshaft Profile Actuator A Control Performance/Stuck Off Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P005B — B Camshaft Profile Actuator A Control Stuck On Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P005C — B Camshaft Profile Actuator A Control Performance/Stuck Off Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P005D — B Camshaft Profile Actuator A Control Stuck On Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0300 — Random/Multiple Cylinder Misfire Detected [High]

Symptoms: Engine shaking, Rough idle, Loss of power, Increased fuel consumption

Impact: Risk of engine damage and catalytic converter failure

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0315 — Crankshaft Position System Variation Not Learned [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0336 — Crankshaft Position Sensor A Circuit Malfunction [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0337 — Crankshaft Position Sensor A Circuit Range/Performance [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0338 — Crankshaft Position Sensor A Circuit Low Input [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0339 — Crankshaft Position Sensor A Circuit High Input [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P033F — Crankshaft/Camshaft Loss Of Synchronization [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0340 — Camshaft Position Sensor A Circuit Malfunction (Bank 1) [High]

Symptoms: Engine stalling, Hard to start, Engine misfires

Impact: Engine may not start or may stall at speed

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0341 — Camshaft Position Sensor Circuit Malfunction [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0342 — Camshaft Position Sensor Circuit Range/Performance [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0343 — Camshaft Position Sensor Circuit Low Input [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0344 — Camshaft Position Sensor Circuit High Input [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0345 — Camshaft Position Sensor A Circuit Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0346 — Camshaft Position Sensor A Circuit Range/Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0347 — Camshaft Position Sensor A Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0348 — Camshaft Position Sensor A Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0349 — Camshaft Position Sensor A Circuit Intermittent Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P034A — Crankshaft Position Sensor - Crankshaft Start Position Incorrect [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P034B — Crankshaft Position Sensor - Crankshaft Direction Incorrect [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0350 — Camshaft Position Sensor Circuit Intermittent [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0365 — Camshaft Position Sensor B Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0366 — Camshaft Position Sensor B Circuit Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0367 — Camshaft Position Sensor B Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0368 — Camshaft Position Sensor B Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0369 — Camshaft Position Sensor B Circuit Intermittent Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P037C — Cold Start Camshaft Profile System Performance [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0386 — Crankshaft Position Sensor B Circuit Malfunction [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0387 — Crankshaft Position Sensor B Circuit Range/Performance [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0388 — Crankshaft Position Sensor B Circuit Low Input [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0389 — Crankshaft Position Sensor B Circuit High Input [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0390 — Camshaft Position Sensor B Circuit Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0391 — Camshaft Position Sensor B Circuit Range/Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0392 — Camshaft Position Sensor B Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0393 — Camshaft Position Sensor B Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0394 — Camshaft Position Sensor B Circuit Intermittent Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03E5 — A Camshaft Position Actuator Position Sensor C Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03E6 — A Camshaft Position Actuator Position Sensor C Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03E7 — A Camshaft Position Actuator Position Sensor C Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03E8 — A Camshaft Position Actuator Position Sensor C Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03E9 — A Camshaft Profile Actuator Position Sensor A Exceeded Learning Limit [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03EA — A Camshaft Profile Actuator Position Sensor B Exceeded Learning Limit [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03EB — A Camshaft Profile Actuator Position Sensor C Exceeded Learning Limit [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03EC — A Camshaft Profile Actuator C Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03ED — A Camshaft Profile Actuator C Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03EE — A Camshaft Profile Actuator C Control Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03EF — A Camshaft Profile Actuator C Control Performance/Stuck Off Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F0 — A Camshaft Profile Actuator C Control Stuck On Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F1 — B Camshaft Profile Actuator C Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F2 — B Camshaft Profile Actuator C Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F3 — B Camshaft Profile Actuator C Control Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F4 — B Camshaft Profile Actuator C Control Performance/Stuck Off Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F5 — B Camshaft Profile Actuator C Control Stuck On Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F6 — B Camshaft Position Actuator Position Sensor C Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F7 — B Camshaft Position Actuator Position Sensor C Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F8 — B Camshaft Position Actuator Position Sensor C Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P03F9 — B Camshaft Position Actuator Position Sensor C Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0400 — Crankshaft Position Sensor B Circuit Intermittent [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1348 — Camshaft Position Sensor B Circuit Malfunction [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1349 — Camshaft Position Sensor B Range / Performance [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1350 — SGC (Cam Position) Sensor Circuit Malfunction/ Crankshaft Position - Camshaft Position Correlation [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2088 — A Camshaft Position Actuator Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2089 — A Camshaft Position Actuator Control Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2090 — B Camshaft Position Actuator Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2091 — B Camshaft Position Actuator Control Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2092 — A Camshaft Position Actuator Control Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2093 — A Camshaft Position Actuator Control Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2094 — B Camshaft Position Actuator Control Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2095 — B Camshaft Position Actuator Control Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23E9 — Camshaft A Position Signal Output Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23EA — Camshaft A Position Signal Output Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23EB — Camshaft A Position Signal Output Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23EC — Camshaft B Position Signal Output Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23ED — Camshaft B Position Signal Output Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23EE — Camshaft B Position Signal Output Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23EF — Camshaft B Position Signal Output Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23F0 — Camshaft B Position Signal Output Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P23F1 — Camshaft B Position Signal Output Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25CA — Intake Camshaft Actuator Park Lock Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25CB — Intake Camshaft Actuator Park Lock Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25CC — Intake Camshaft Actuator Park Lock Control Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25CD — Intake Camshaft Actuator Park Lock Control Circuit/Open Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25CE — Intake Camshaft Actuator Park Lock Control Circuit Low Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25CF — Intake Camshaft Actuator Park Lock Control Circuit High Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25DD — A Camshaft Position - Stuck In Locked Position Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25DE — A Camshaft Position - Unable to Achieve Locked Position Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25DF — A Camshaft Position Control Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E0 — A Camshaft Position - Stuck In Locked Position Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E1 — A Camshaft Position - Unable to Achieve Locked Position Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E2 — A Camshaft Position Control Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E3 — B Camshaft Position - Stuck In Locked Position Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E4 — B Camshaft Position - Unable to Achieve Locked Position Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E5 — B Camshaft Position Control Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E6 — B Camshaft Position - Stuck In Locked Position Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E7 — B Camshaft Position - Unable to Achieve Locked Position Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P25E8 — B Camshaft Position Control Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2614 — Camshaft A Position Signal Output Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2615 — Camshaft A Position Signal Output Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2616 — Camshaft A Position Signal Output Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2617 — Crankshaft Position Signal Output Circuit/Open [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2618 — Crankshaft Position Signal Output Circuit Low [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2619 — Crankshaft Position Signal Output Circuit High [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B33 — A Camshaft Profile Actuator B Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B34 — A Camshaft Profile Actuator B Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B35 — A Camshaft Profile Actuator B Control Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B36 — A Camshaft Profile Actuator B Control Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B37 — A Camshaft Profile Actuator B Control Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B38 — A Camshaft Profile Actuator B Control Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B39 — B Camshaft Profile Actuator B Control Circuit/Open Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B3A — B Camshaft Profile Actuator B Control Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B3B — B Camshaft Profile Actuator B Control Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B3C — B Camshaft Profile Actuator B Control Circuit/Open Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B3D — B Camshaft Profile Actuator B Control Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B3E — B Camshaft Profile Actuator B Control Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B3F — A Camshaft Position Actuator Position Sensor B Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B40 — A Camshaft Position Actuator Position Sensor B Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B41 — A Camshaft Position Actuator Position Sensor B Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B42 — A Camshaft Position Actuator Position Sensor B Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B43 — A Camshaft Position Actuator Position Sensor B Circuit Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B44 — A Camshaft Position Actuator Position Sensor B Range/Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B45 — A Camshaft Position Actuator Position Sensor B Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B46 — A Camshaft Position Actuator Position Sensor B Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B47 — B Camshaft Position Actuator Position Sensor B Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B48 — B Camshaft Position Actuator Position Sensor B Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B49 — B Camshaft Position Actuator Position Sensor B Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B4A — B Camshaft Position Actuator Position Sensor B Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B4B — B Camshaft Position Actuator Position Sensor B Circuit Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B4C — B Camshaft Position Actuator Position Sensor B Range/Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B4D — B Camshaft Position Actuator Position Sensor B Circuit Low Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B4E — B Camshaft Position Actuator Position Sensor B Circuit High Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B4F — A Camshaft Profile Actuator B Control Performance/Stuck Off Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B50 — A Camshaft Profile Actuator B Control Performance/Stuck Off Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B51 — B Camshaft Profile Actuator B Control Performance/Stuck Off Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B52 — B Camshaft Profile Actuator B Control Performance/Stuck Off Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B53 — A Camshaft Profile Actuator B Control Stuck On Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B54 — A Camshaft Profile Actuator B Control Stuck On Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B55 — B Camshaft Profile Actuator B Control Stuck On Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2B56 — B Camshaft Profile Actuator B Control Stuck On Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C05 — A Camshaft Profile Actuator Position Sensor A Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C06 — A Camshaft Profile Actuator Position Sensor A Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C07 — A Camshaft Profile Actuator Position Sensor A Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C08 — A Camshaft Profile Actuator Position Sensor A Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C09 — A Camshaft Profile Actuator Position Sensor B Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C0A — A Camshaft Profile Actuator Position Sensor B Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C0B — A Camshaft Profile Actuator Position Sensor B Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C0C — A Camshaft Profile Actuator Position Sensor B Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C0D — A Camshaft Profile Actuator Position Sensor C Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C0E — A Camshaft Profile Actuator Position Sensor C Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C0F — A Camshaft Profile Actuator Position Sensor C Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C10 — A Camshaft Profile Actuator Position Sensor C Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C12 — B Camshaft Profile Actuator Position Sensor A Circuit Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C13 — B Camshaft Profile Actuator Position Sensor A Range/Performance Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C14 — B Camshaft Profile Actuator Position Sensor A Circuit Low Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C15 — B Camshaft Profile Actuator Position Sensor A Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C16 — B Camshaft Profile Actuator Position Sensor B Circuit Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C17 — B Camshaft Profile Actuator Position Sensor B Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C18 — B Camshaft Profile Actuator Position Sensor B Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C19 — B Camshaft Profile Actuator Position Sensor B Circuit High Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C1A — B Camshaft Profile Actuator Position Sensor C Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C1B — B Camshaft Profile Actuator Position Sensor C Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C1C — B Camshaft Profile Actuator Position Sensor C Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2C1D — B Camshaft Profile Actuator Position Sensor C Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34AC — A Camshaft Position Actuator Position Sensor A Circuit Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34AD — A Camshaft Position Actuator Position Sensor A Range/Performance Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34AE — A Camshaft Position Actuator Position Sensor A Circuit Low Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34AF — A Camshaft Position Actuator Position Sensor A Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B0 — A Camshaft Position Actuator Position Sensor A Circuit Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B1 — A Camshaft Position Actuator Position Sensor A Range/Performance Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B2 — A Camshaft Position Actuator Position Sensor A Circuit Low Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34B3 — A Camshaft Position Actuator Position Sensor A Circuit High Bank 2 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34BC — B Camshaft Position Actuator Position Sensor A Circuit Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34BD — B Camshaft Position Actuator Position Sensor A Range/Performance Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34BE — B Camshaft Position Actuator Position Sensor A Circuit Low Bank 1 [High]

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34BF — B Camshaft Position Actuator Position Sensor A Circuit High Bank 1 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C0 — B Camshaft Position Actuator Position Sensor A Circuit Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C1 — B Camshaft Position Actuator Position Sensor A Range/Performance Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C2 — B Camshaft Position Actuator Position Sensor A Circuit Low Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C3 — B Camshaft Position Actuator Position Sensor A Circuit High Bank 2 **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P34C8 — Camshaft Position Control Module Performance **[High]**

Symptoms: Possible reduced performance, Check Engine Light on

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

Transmission

P0219 — Engine Over Speed Condition [Critical]

Symptoms: Check Engine Light on, Possible reduced performance

Impact: Reduced performance and possible secondary system impact

Recommendation: Stop driving immediately and seek emergency repair

Vehicle Speed & Control

P0068 — MAP/MAF - Throttle Position Correlation [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0120 — Throttle Position Sensor/Switch A Circuit Malfunction [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0121 — Throttle Position Sensor/Switch A Circuit Range/Performance Problem [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0122 — Throttle Position Sensor/Switch A Circuit Low Input [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0123 — Throttle Position Sensor/Switch A Circuit High Input [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0124 — Throttle Position Sensor/Switch A Circuit Intermittent [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P0520 — Closed Throttle Position Switch Malfunction [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P060E — Internal Control Module Throttle Position Performance [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1125 — Throttle position sensor out of range [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1126 — Throttle Position (TP) Sensor Circuit Intermittent High Voltage [High]

Symptoms: Electrical issues, Hesitation on acceleration, Rough idle, Starting problems

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1127 — Throttle Position (TP) Sensor Circuit Intermittent Low Voltage [High]

Symptoms: Electrical issues, Hesitation on acceleration, Rough idle, Starting problems

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1128 — Throttle Position Sensor In Range But Higher Than Expected [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1129 — Throttle Position Sensor Out Of Self Test Range [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1130 — Throttle position sensor intermittent [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1131 — Throttle Position (Narrow Range) Sensor Circuit Malfunction [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1229 — Throttle Position Sensor B Out Of Self Test Range [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1578 — Throttle Position Not Available [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1579 — Throttle Position Sensor Disagreement btwn Sensors [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P1601 — Throttle Control Unit Throttle Position Malfunction [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P212A — Throttle Position Sensor/Switch G Circuit [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P212B — Throttle Position Sensor/Switch G Circuit Range/Performance [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P212C — Throttle Position Sensor/Switch G Circuit Low [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P212D — Throttle Position Sensor/Switch G Circuit High [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P212E — Throttle Position Sensor/Switch G Circuit Intermittent [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2620 — Throttle Position Output Circuit/Open [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2621 — Throttle Position Output Circuit Low [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving

P2622 — Throttle Position Output Circuit High [High]

Symptoms: Hesitation on acceleration, Rough idle

Impact: Reduced performance and possible secondary system impact

Recommendation: Schedule repair within 24-48 hours; avoid extended driving