PHARMACEUTICAL MANUFACTURING

INCIDENT / DEVIATION NOTIFICATION

Sample training document for RootIQ AI extraction and investigation workflow

Document reference	QMS-DEV-2026-0118	**Report date**	06-Nov-2026
Site	API Plant Alpha – Hyderabad	**Department**	Solid Oral Dosage
Batch number	BATCH-API-26-041	**Product**	Paracetamol High-Density Granules
Equipment	Fluid Bed Dryer FBD-204	**Process stage**	Final drying

1. Incident description

During final drying of batch **BATCH-API-26-041** in Fluid Bed Dryer **FBD-204**, the product temperature was recorded above the approved operating range. The batch record lists the target product-temperature range as **48–52 °C**. The historian trend shows a peak reading of **56.8 °C** and indicates that the temperature remained above 52 °C for approximately **22 minutes** between 10:14 and 10:36 on 04-Nov-2026.

The operator noticed the high-temperature alarm during the run and informed the shift supervisor. The drying step was paused. The batch was placed on quality hold pending investigation. No disposition decision has been recorded in this notification.

2. Expected versus observed condition

Parameter	Approved / expected	Observed
Product temperature	48–52 °C	Peak 56.8 °C
Time outside range	Not applicable	Approximately 22 minutes
Event window	Not applicable	04-Nov-2026, 10:14–10:36

3. Immediate containment actions

At approximately 10:38 on 04-Nov-2026, the operator paused the drying cycle and notified the shift supervisor. At 10:52, the production supervisor entered a quality-hold instruction for the batch in the batch record. The material remains segregated in the designated hold area as of the time this notification was prepared.

4. Initial observations and available evidence

The equipment historian export (reference: **HIST-FBD204-0411**) contains the temperature trend for the event window. The executed batch record (reference: **EBR-API-26-041**) contains the approved temperature range and operator entries. The shift log records that an alarm was acknowledged at 10:17. These records have been identified as available investigation evidence; their full review and attachment to the investigation are still pending.

The notification does not establish why the temperature increased. No confirmed equipment failure, sensor malfunction, procedural error, or material-related cause has been determined. These possibilities must not be treated as findings without supporting evidence.

5. Information not available in this notification

- Deviation classification / severity and formal deviation ID
- Name and ID of the operator and shift supervisor
- Equipment maintenance, calibration, and alarm-history review

• Raw historian data and confirmation of sensor status

• Detailed review of the executed batch record and process parameters

• Impact assessment, including any relevant quality-test results

• Root cause, contributing factors, and final batch disposition

• Corrective and preventive actions, owners, and due dates

6. Investigation status

Status: Open – investigation required.
Containment: Batch placed on quality hold.
Root cause: Not determined.
CAPA: Not yet assigned.
Approval: This notification has not been approved as a final investigation report.

IMPORTANT: This is a fictional sample document created for software testing and demonstration. It is not a real manufacturing record, validated quality document, or evidence of an actual deviation.

End of sample document · RootIQ test input · Version 1.0