## 7 Synthetic scanned procedure

### 7.1 Gadget release

The Test Function shall send a GADGET RELEASE COMMAND message

to the UE when the gadget context is no longer required.

Upon receipt the UE shall stop timer T3540 and enter the idle state.