Autonomous Infrastructure Inspection Report

Field	Details
Report Date	2026-04-03 03:30:20
Source File	pothole_145.jpg
Models Used	YOLOv8 Segmentation + YOLOv8 Detection
System	Autonomous Infrastructure Inspection AI

Detection Summary

Defect Type	Status	Count
Road Crack	**DETECTED**	2
Pothole	**DETECTED**	7

Detection Result Image

The image below shows the annotated output with all detected defects highlighted.



Recommendations

- Road cracks detected — schedule crack sealing/filling within 30 days.
- Potholes detected — immediate patching required to prevent vehicle damage.

- Re-inspect the flagged area after repairs are completed.
- Maintain inspection logs for infrastructure health tracking.