## **QC Test**


The *QC Test* screen lets you define various quality control tests by defining specific characteristics for testing the quality of an item. Once a test is defined, it can be assigned to the intended inventory item(s) via the *QC Item Test* screen, and have its expected results defined. You can also specify the default QC User who will perform the QC test.

QC testing must be planned and thought out to decide things like what exactly you are testing and testing for, the way the test is going to be run and applied, and the steps required to do so. All these scenarios should be clear in your mind before defining test(s). Tests usually take the form of 'does this product meet requirements?', and are passed/failed accordingly.

Go To: Quality Control  $\rightarrow$  Quality Control  $\rightarrow$  QC Test.

## QC Test - Dashboard

You can manage and create QC Tests from this dashboard. By default, the system displays all the existing QC Test records as maintained for your business/company. You can click on any of the QC Test record to view its details.




The *QC Test* dashboard contains many elements that occupy 100% of the browser window. Resizing the window would resize the elements to fit. The elements can be rearranged, i.e., docked, resized, grouped, and stacked. The header and the side panel can't be rearranged.

Using the Action button from the dashboard you can:

- Copy an existing record to create new one
- Delete selected multiple record(s)


After you select all the columns of the QC Test dashboard, the middle grid displays the selected columns.



The QC Test dashboard provides a clear vision of the created records in a read-only mode. You can view the QC Test records as per the number of pages provided per page.

### QC Test Screen – Add Mode

To add a new QC Test to your BatchMaster database, click on the + Add Test button. The system displays the QC Test screen, where you can create a new record.



#### **Screen Fields:**

**Test Id:** This is the unique Identification code for the respective QC test defined at the screen. This is used in selecting the record at various screens of BatchMaster. Even the selection criteria for generating reports recognize this ID only. It is a mandatory field and shouldn't be duplicated.

**Test Description:** This field displays the description associated with the Test Id. This is a read-only field.

**Test Unit:** This field displays the unit of measure in which the result of the respective QC Test is interpreted. This unit of measure is displayed on various reports. It is to be noted that this unit has no relationship to the various units that are maintained at the *Units* screen of the *Common Data* module.

**Destructive Unit:** Checking or un-checking this box specifies whether the test is destructive in nature or not. When a destructive test is done, the user needs to manually specify the quantity of the material scrapped due to a destructive test at *Inventory QC/Sales QC/Purchase QC* screen.

**Test-Result File Template:** This is the path of the Template-file that is used for storing the details of this test-result.

# **Creating a QC Test**

- 1. Open the QC Test dashboard.
- 2. Click on the +Add Test button to open a new blank record.

- 3. Enter the Test ID in the *Test Id* field.
- 4. Enter the Test ID's description in the *Test Description* field.
- 5. Enter a value in the *Test Unit* field, if needed.
- 6. If this is a destructive test, click the *Destructive Test* checkbox. Otherwise, leave it unchecked.
- 7. Specify a path in the *Test-Result File Template* field, if needed.
- 8. Click the *Save* button to save the record.