Health, Safety, Quality and Environmental Site Inspection

Site:	Weetabix Burton AP1 / Main	Completed By:	John Cord	Date:	4-Sep-21	
Work Area:	AP6 foyer	Job Description:	Running and fitting telecom cables			
Supervisor:	Graham Cragg	Inspector:	John Cord	Туре:	Installation	

Supervisor:	Granam Cragg	Inspector:	John Cord	Type:	istaliation
		Interventions	Comment	Completed	Action Taken
A. Working Stan	ndards				
1. Work At Height		0		1	
2. Lifting Operations - Crane, Fork Lift Truck, Hoists etc		0			
3. Certification - Daily Checksheets for MEWP and FLT		0			
4. Confined Space Work		0			
5. Electrical Work		0			
B. Quality					
6. Site Set Up & Apperance, Signage		1	A frame "men at work " signs i place	n Yes	Good practice
7. Paperwork (Permits, Risk Assessments, Method Statement,		1	Documentation all in order and signed	Yes	Commended guys
8. Certification - Training, Insurance Inspection, Induction Current		0			
C. Site Rules					
9. Hot Work		0			
10. Isolation and Loc	k Offs	0			
11. Fire Exits and Escape Routes		1	Good housekeeping	Yes	n//a
12. Awareness - Fire	Exit, Assembly Point	0			
D. Environmenta	al				
13. Waste Management		0			
14. Product Contamination		0			
15. COSHH & Asbestos		0			
E. Protection Of Individuals					
16. PPE		0			İ
17. Manual Handling		0			
18. Other Contractors		0			
F. Tools, Cables & Other Equipment					
19. Power Tools, Cabl	les & Other Equipment	0			
20. Voltage Detector	Checked	0			
21. Tools Used Fit For	r Purpose	0			
G. Miscellaneous					
22. Company Vehicles	S	0			
23. Fire Precautions		0			
24. Workshop Conditions		0			
Total Interventi	ons By Section				
A. Working Standards	<u> </u>	0	1		
B. Quality		2			
C. Site Rules		1			
			1		

0

0

0

D. Environmental

G. Miscellaneous

E. Protection Of Individuals

F. Tools, Cables & Other Equipment

Overall 3