

Incident Report INC_005 — Hydraulic System Failure

Downtime Incident Report · Severity: Major

Doc ID	INC-005
Date of Incident	2026-06-18
Plant / Location	Plant A (Pune)
Line / Machine	Press Line — Press_Line_11
Shift	Morning
Operator on Duty	OP-036
Downtime Code	DT-01 — Hydraulic System Failure

1. Summary

On 2026-06-18, machine Press_Line_11 (Press Line) at Plant A, Pune experienced an unplanned stoppage of 233 minutes during the Morning shift, logged under downtime code DT-01 (Hydraulic System Failure). This is classified Major severity per the Error_Code_Handbook and exceeds the 120-minute incident-filing threshold defined in Plant_Maintenance_Policy section 5.

2. Description of Failure

A high-pressure hydraulic hose on the main ram cylinder developed a pinhole leak, causing progressive pressure loss and an automatic hydraulic-fault trip.

3. Root Cause

Hose reached end of service life; scheduled replacement interval had not yet been reached but abrasion against an adjacent frame member accelerated wear.

4. Corrective Action Taken

Replaced the hose assembly per Hydraulic_Maintenance_SOP, re-bled the circuit, and added a protective wear sleeve at the contact point.

5. Downtime Impact

Metric	Value
Total downtime	233 minutes
Downtime code	DT-01 — Hydraulic System Failure
Machine	Press_Line_11 (Press Line)
Shift / Operator	Morning / OP-036

6. Preventive Follow-Up

- Work order raised to inspect equivalent hydraulic components on sister machines of the same type.
- Reviewed against Lubrication_Schedule and PM_Guide to confirm hydraulic PM interval was followed.
- Corrective action and parts usage logged in CMMS and cross-referenced to Hydraulic_Maintenance_SOP.