PUMP INSPECTION REPORT
Facility: Industrial Plant Unit 4
Equipment ID: PUMP-402 (Centrifugal Feed Pump)
Inspection Date: 2026-08-25
Inspector: Maintenance Team A

1. Visual Inspection:
- Minor cavitation erosion observed on impeller edges.
- Mechanical seal shows no signs of active leakage.

2. Vibration and Temperature Analysis:
- Drive end bearing temperature: 68°C (Normal < 75°C).
- Peak vibration velocity: 3.8 mm/s RMS (Warning threshold: 4.5 mm/s).

3. Recommended Actions:
- Schedule impeller replacement during the next planned quarterly overhaul.
- Replace lubricant in bearing housing within 100 operating hours.