


Updated PVC frame with new motor positions and propeller positions



Original PVC render with ineffective motor positions



Waterproof electronics enclosure