ストレージファームウェアバンドル 2.27 リリースノート

HCI

Michael Wallis, Dave Bagwell, amitha, Aksel Davis, Ann-Marie Grissino
June 21, 2021

This PDF was generated from https://docs.netapp.com/ja-jp/hci/docs/rn_storage_firmware_2.27.html on July 01, 2021. Always check docs.netapp.com for the latest.

目次

ストレージファームウェアバンドル 2.27 リリースノート 1
新機能 1
BMC の新機能 2
解決済みの問題 2
セキュリティの脆弱性を解決 3
既知の問題 3

ストレージファームウェアバンドル 2.27 リリースノート

Element 12.0 以降および管理サービスバージョン 2.14 以降では、 NetApp Hybrid Cloud Control の UI と REST API を使用して、ストレージノードでファームウェアのみのアップグレードを実行できます。この手順では、 Element ソフトウェアはアップグレードされず、 Element のメジャーリリース以外のバージョンのストレージファームウェアもアップグレードできます。

> Element ソフトウェアバージョン 12.0 を実行している H610S ストレージノードについては、ストレージファームウェアバンドル 2.27 にアップグレードする前に「 D パッチ」「 St-909 」を適用する必要があります。アップグレード前に、ネットアップサポートに問い合わせて D パッチを入手します。

新機能

ストレージファームウェアバンドルバージョン 2.27 には、セキュリティ脆弱性の修正など、さまざまなバグ修正と新機能が含まれています。の手順に従って、ストレージファームウェアをアップグレードできます "ストレージファームウェアをアップグレードします"。

ファームウェアコンポーネントが更新されました

このファームウェアパッケージには、次のファームウェアバージョンが含まれています。これらのファームウェアバージョンは、太字で更新されています。

コンポーネント	**Dell R630**	**H410S**	**H610S**
BIOS	該当なし	NA2.1	3B03
BMC の場合	該当なし	* 6.8400 *	* 3.84.07 *
NIC / Mellanox	-	14.21.1000	14.22.1002
RMS200	aeb8cc	7d8422bc	-
RMS300	7d8422bc	7d8422bc	-
NVDIMM 、スマート	-	-	3.1
bpm 、 SMART	-	-	2.16
NVDIMM 、 Micron Gen1	-	-	26.2c
NVDIMM 、 Micron Gen2	-	-	25.3c
PGEM 、 Micron 社	-	-	1.40
PM863 、 SED	GXT5404Q	GXT5404Q	-
PM863 、 NSED	GXT5103Q	GXT5103Q	-
PM883 、 SED	HXT7104Q	HXT7104Q	-
Hawk-4 、 SED	8ENP7101	8ENP7101	-

コンポーネント	**Dell R630**	**H410S**	**H610S**
Hawk-4 、 NSED	8ENP6101	8ENP6101	-
PM963 、 SED	-	-	CXV8202Q
PM963 、 NSED	-	-	CXV8501Q
PM983 、 SED	-	-	* EDA5302Q *
PM983 、 NSED	-	-	* EDA5600Q *
CD5 、 SED	-	-	0108.
CD5 、 NSED	-	-	0108.
CD5 、 FIPS	-	-	0108.

BMC の新機能

このリリースで追加された BMC の新機能と変更点を次に示します。

- （ H610S ）を使用すると、 initrd サポートにより、ブート時に初期 RAM ディスクをロードできるようになりました
- （ H610S ） X.509 証明書に関する SSL ヘルプメッセージを更新しました
- （ H610S ）セキュリティを解決するために TLS 1.0 および 1.1 のサポートが無効になりました 脆弱性
- （ H610S 、 H410S ）で、 Redfish API を使用してリモートメディアをマウントできるようになりました
- （ H610S ） HTML5 Web ブラウザの BMC 管理のサポートが追加されました
- （ H610S ）リモートデータセンターの監視と管理に役立つリモート syslog のサポートが追加されました

解決済みの問題

このリリースで解決された問題は次のとおりです。

問題	説明
該当なし	デバッグユーザの sysadmin は、 BMC をリセットしたあとで SSH を使用してログインできます。
該当なし	コンソールを使用して BMC の IP アドレスに ping を実行しても、 BMC は応答しません。
該当なし	AC 電源再投入時のストレステスト中に、 SOLSSH 設定ファイルのアクセス許可が失われます。
CSESF-116	AC 電源再投入時のストレステスト中に、 BMC ログに CPU 温度警告 "PROCHOT" が記録されます。
CSESF-121	サービスアカウントの作成と更新の API に予想よりも時間がかかります。
CSD-3321/CSESF-129	H610S BMC がハングし、「 BMC Self Test Failed 」というエラーでアクセスできなくなることがあります。

問題	説明
CSESF-197	BMC Web UI インベントリ API から正しいメモリシリアル番号の形式が返されません。

セキュリティの脆弱性を解決

このリリースで解決されたセキュリティの脆弱性は次のとおりです。

H410S BMC 6.84.00

- CVE-2016-16649
- CVE-2016-16650
- CVE-2016-6260

H610S BMC 3.84.07

- CVE-2018-1552
- CVE-2017-1547 、 CVE-2018-1563
- CVE-2019-5482
- CVE-2018-15903
- CVE-2018-20843
- CVE-2019-14821 、 CVE-2019-15916 、 CVE-2018-16413
- CVE-2017-10638 、 CVE-2019-10639
- CVE-2017-11478 、 CVE-2017-11479 、 CVE-2018-11477
- CVE-2019-12819
- 2019 年から 14835 、 2019 年から 14814 、 2019 年から 14816 、 2019 年から 16746 のいずれかです
- CVE-20119-19062
- CVE-20119-19922 、 CVE-2018-20054
- 2019 年から 19447 年、 2019 年から 19767 年、 2019 年から 10220 年の間に

既知の問題

このリリースで確認されている既知の問題はありません。

詳細については、こちらをご覧ください

- "vCenter Server 向け NetApp Element プラグイン"
- "NetApp HCI のリソースページ"

Copyright Information

Copyright © 2021 NetApp, Inc. All rights reserved. Printed in the U.S. No part of this document covered by copyright may be reproduced in any form or by any means-graphic, electronic, or mechanical, including photocopying, recording, taping, or storage in an electronic retrieval system-without prior written permission of the copyright owner.

Software derived from copyrighted NetApp material is subject to the following license and disclaimer:

THIS SOFTWARE IS PROVIDED BY NETAPP “AS IS” AND WITHOUT ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, WHICH ARE HEREBY DISCLAIMED. IN NO EVENT SHALL NETAPP BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

NetApp reserves the right to change any products described herein at any time, and without notice. NetApp assumes no responsibility or liability arising from the use of products described herein, except as expressly agreed to in writing by NetApp. The use or purchase of this product does not convey a license under any patent rights, trademark rights, or any other intellectual property rights of NetApp.

The product described in this manual may be protected by one or more U.S. patents, foreign patents, or pending applications.

RESTRICTED RIGHTS LEGEND: Use, duplication, or disclosure by the government is subject to restrictions as set forth in subparagraph (c)(1)(ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.277-7103 (October 1988) and FAR 52-227-19 (June 1987).

Trademark Information

NETAPP, the NETAPP logo, and the marks listed at http://www.netapp.com/TM are trademarks of NetApp, Inc. Other company and product names may be trademarks of their respective owners.