

## **SCHEDULE A - LIST OF BARRIERS FOR ASSESSMENT**

**Table 1.** Barrier assessment locations and description.

<b>Table 1.</b> Barrier assessment locations and description.								
	modelled		Road					
aggregated_	_crossing		Surfac	Zone 11				
crossings_id	_id	Waterbody	е Туре	Easting	Northing	Comments		
1024735443	24735443	Abruzzi Creek	rough	5591423	638867			
1004603480	4603480	Bean Creek	loose	5464640	650539			
1004606347	4606347	Bean Creek	loose	5463819	650415			
		Trib to Bean						
1004605499	4605499	Creek	paved	5463543	650057			
						Probably deactivated but not		
1004603553	4603553	Bighorn Creek	loose	5447429	663230	certain		
1004606926	4606926	Bighorn Creek	rough	5445241	664112			
1004600533	4600533	Chauncey Creek	rough	5554160	656890			
						Previously assessed in PSCIS (ID 61504). Needs reassessment. comments from PSCIS: "Old concrete from old bridge in streambed. Creates somewhat of a barrier." Reassess for pass-ability using professional judgment/analysis, since it doesn't fit the provincial		
61504	24706507	Coal Creek	loose	5483687	645313	protocol.		
1004606545	4606545	Cummings Creek	loose	5520738	644862			
62181	62181	Dry Creek	Rail	656409	5544755	Habitat confirmations completed by Masse in 2013 (PSCIS ID 62181) but culverts scored as passable. Reassess now that culverts have aged. Habitat confirmations completed by Masse in 2013 (PSCIS ID 62182) but culverts		
						scored as passable. Reassess		
62182	62182	Dry Creek	Paved	656391	5544771	now that culverts have aged.		
1004600762	4600762	Fording River	loose	5562574	651282			
1004603334	4603334	Fording River	loose	5566706	651461			
1004606284	4606284	Fording River	loose	5571951	652990			
1004602514	4602514	Harmer Creek	rough	5517830	659393			
		Trib to Harmer	Over-					
1004601280	4601280	Creek	grown	5517583	659427			
1004603413	4603413	Henretta Creek	rough	5567436	654825			
1004604677	4604677	Henretta Creek	loose	5566424	652123			
100-00-077								



	modelled		Road			
aggregated_	_crossing		Surfac	Zone 11		
crossings_id	_id	Waterbody	е Туре	Easting	Northing	Comments
1024706614	24706614	Henretta Creek	loose	5566732	653180	May be a bridge
1004603793	4603793	Lodgepole Creek	rough	5462235	663619	
1004606370	4606370	Lodgepole Creek	paved	5462562	664905	
1004606398	4606398	Lodgepole Creek	paved	5462152	665796	
		Trib to Lodgepole				
1004601984	4601984	Creek	rough	5458678	654302	
		Trib to Lodgepole				
1004603791	4603791	Creek	rough	5461227	660586	
		Trib to Lodgepole				
1004606411	4606411	Creek	rough	5459547	658765	
		Trib to	Sea-			
1024733953	24733953	Lodgepole Creek	sonal	5461435	652221	Might be a bridge
1004607022	4607022	McCool Creek	loose	5499879	648168	
1004601704	4601704	Morrissey Creek	rough	5473852	650166	
1004602163	4602163	Morrissey Creek	rough	5475661	651609	
1004601993	4601993	Rabbit Creek	rough	5431721	656655	
1004601995	4601995	Rabbit Creek	rough	5431860	655890	
1004602359	4602359	Rabbit Creek	rough	5431721	655618	
		Trib to Cadorna				
1004603432	4603432	Creek	rough	5591178	639196	
		Trib to Ewin				
1004607449	4607449	Creek	rough	5547544	659284	
		Trib to Wigwam				
1004602646	4602646	River	loose	5452095	647364	
		Trib to Wigwam				
1004605216	4605216	River	loose	5449516	647730	
		Trib to Wigwam	l .			
1004605338	4605338	River	loose	5436172	658388	
400463-33-	460500	Trib to Wigwam	l .	F 404004	669617	
1004605937	4605937	River	loose	5431294	662247	
1004606433	4606430	Trib to Wigwam		E 4 4 6 7 2 2	C40404	
1004606129	4606129	River	loose	5446732	649481	
1004602949	4602949	Weigert Creek	loose	5534524	647247	
1004606007	4606007	Weigert Creek	loose	5534676	647156	
1024725040	24725040	Maigrant Const.	Sea-	FE340F0	CE0040	
1024735049	24735049	Weigert Creek	sonal	5531958	650010	



**Table 2.** Dam locations and descriptions.

aggregated _crossings_i	dam _id	Waterbody	Water License No.	Water License Holder	(Zone 11) Easting	Northing	Comments
							Dam designed as side
							channel and not part of main
				District			flow of creek. Verify that it
		Boivin		of			does not block mainstem
1100002606	n/a	Creek	C059359	Elkford	647275	5541987	flows.
				Teck			
				Coal			
		Harmer		Elkview			
1100001086	n/a	Creek	C040628	Ops	657051	5522119	
				Ricky			0.3 m dam immediately
				and			upstream of PSCIS crossing
				Sheri			197542. Assess whether dam
		Hartley		Hutchin-			is passable to fish. No habitat
n/a	2348	Creek	F010679	son	643521	5490697	confirmation required.