## **QA AUDIT - MIXED INFRACTIONS**

Infraction 1: Pole buried 4 feet deep.

Infraction 2: Grade 8.8 bolts used.

Infraction 3: Copper conductors installed.

Infraction 4: Clearance of 10 feet.

Infraction 5: Blue paint on equipment.