### The reason of LSI ESD damage

## **Electrostatic Discharge (ESD)**



Discharge current flows into LSI



Generation Generation of of heat high voltage

**Melting** 

Dielectric breakdown

# **Metallic objects:**

Tweezers, Pliers, Screwdriver, Charged IC socket, etc.



**Discharge** 


# **Charged conductor:**

**Human body Tools** etc.


**Discharge** 

Charged **Object:** LSI,

**Boards** 



# The cause of electrostatic discharge



# The cause (1) of electrostatic charging

**Triboelectrification** 

LSI, PWB, Humán body, **Metallic tools** (Conductors)

Charge

**Discharge** 


**Electrostatic** induction

Insulating material



Charge





# The cause (2) of electrostatic charging (Example of charge of LSI)


The conductors near the charged material is charged by electrostatic induction

LSI, PWB, human body, and metallic tools near any charged material



Generation of electrostatic induction

### **Electrostatic induction**



# The cause (2) of electrostatic charging (Example of human body)

#### **Example of human body sit on the charged chair** Charged human body **Electrostatic induction** (Amount of electric charge is zero) No Charged charged Sit chair down human body **Human body** is charged by discharge of negative charge.

# The cause (3) of electrostatic charging

# Direct charging by other charged conductors

©2009. Renesas Technology Corp., All rights reserved.

If the charged conductor touches another conductor, it will be charged.

LSI, PWB, and tools



Charge and discharge will be occurred at the same time.

