

Triangles: no failure within 240 min

Illustrative, not fire ratings: the wall model has not yet been validated against a loaded wall test.