

Flow Restriction Procedure

Threshold

40 L/min

Possible Causes

Blocked filter

Closed valve

Pump wear

Pipeline deposits

Operator Action

Inspect filter.

Verify valve positions.

Flush pipeline.

Replace worn impeller.