

One sensor just went dark.

The farm keeps running.

Hour 22

A judge will walk up to your station and physically remove one Modbus sensor from your Raspberry Pi. No warning. No countdown.

The moment it goes offline, your system must know. A communication timeout must be detected, an alert must appear on your dashboard, and — critically — everything else must keep running exactly as before. The remaining sensors keep reading. The automation keeps working. The dashboard stays up.

Do not crash. Do not hang. Do not require a manual restart. Operate in fail-safe mode and keep the farm alive.

"Resilience is not about never failing. It's about what your system does the moment something does."

Your Objectives :

- Detect communication timeout when sensor is removed
- Generate an alert indicating the sensor has been removed
- Continue operating safely : system must keep running without the missing sensor

Your Submission :

- Photo of disconnected sensor and alerts showing sensor is removed
- SVN commit -m "Challenge5 : Completed" --username [username]