MATRIX: Checklist Standard measurements

Must-Dos = Red, optional = Blue

Start of measurement day:

- 1. Voltage Scan Dark (all later used voltages need to be recorded here!)
- 2. Voltage Scan signal (signal close to usual measurement fluence) = choice of measurement voltage
- 3. Voltage-dependent linearity
- 4. x- or y-translated measurement through diffused beam (several overlapping positions are needed)

End of measurement day:

- 1. Voltage Scan Dark (as reference)
- 2. Voltage Scan signal (signal close to usual measurement fluence)
- 3. Voltage-dependent linearity
- 4. x- or y-translated measurement through diffused beam (several overlapping positions are needed)