## Types of [[Finite State Machines]]


## **Moore Machines**

- next state = function of present state and input
- output = function of present state


## **Mealy Machines**

- next state = function of present state and input
- output = function of present state and input
- mealy machines have different outputs for the same state
  - output written outside of state circle
  - next to state transition
  - value of input affect timing diagram

state	in	output
Α	0	4
Α	1	4
В	0	3
В	1	1
С	0	2
С	1	0



- machine combinations
  - multiple moore machines cause no problems



- moore with mealy machine cause no problems
- two mealy machine may cause problems
  - \* one needs to avoid combinational loops

