
Colibri Scan Report



Licence Plate
9547 LPV

VIN

Date
19.10.2026 16:27

Car Brand


Car Model

Calculation Method
GERMANY

Language
ENGLISH GB

Customer
Allianz-Allianz

Total Dents
All: 618 Ø: 30mm



Colibri Scan Report

Left


	10mm	20mm	30mm	40mm	50mm	60mm	70mm	80mm	Total	Φ
Fender Front Left				1					1	40
Door Front Left	1								1	10
Door Rear Left	-	-	-	-	-	-	-	-	-	-
Fender Rear Left	1	9	4		1				15	24
Roof Spar Left			1		1				2	40

Horizontal


	10mm	20mm	30mm	40mm	50mm	60mm	70mm	80mm	Total	Φ
Bonnet	6	25	23	17	8	15	1	2	97	36
Roof	23	162	130	61	33	16	6	1	432	30
Trunk Top		7	2			1			10	26
Trunk Bottom	-	-	-	-	-	-	-	-	-	-

Right


	10mm	20mm	30mm	40mm	50mm	60mm	70mm	80mm	Total	Φ
Fender Front Right		1	1	1					3	30
Door Front Right		2	1	2					5	30
Door Rear Right		3	12	6	2				23	33
Fender Rear Right		7	9		3				19	29
Roof Spar Right	1	2	4	2	1				10	30




Colibri Scan Report




Fender Front Left Left



Fender Front Right Right



Door Front Left Left




Door Front Right Right


Colibri Scan Report

No Image


Door Rear Left Left



Door Rear Right Right




Fender Rear Left Left



Fender Rear Right Right

Colibri Scan Report



Roof

Colibri Scan Report




Roof Spar Left Left




Roof Spar Right Right

Colibri Scan Report



Bonnet



Trunk Top

No Image

Trunk Bottom

Colibri Scan Report




Front Upper Left



Front Upper Right



Right _6



Right _5



Right _4



Right _3

Colibri Scan Report



Right _2



Right _1



Back Upper Right



Back Upper Left



Left _1




Left _2

Colibri Scan Report




Left _3



Left _4



Left _5



Left _6



Left _7



Top Front

Colibri Scan Report



Top Back