



Production per type



Failures per production



H
L
M

339
Total failures

46
TWF Total


19
RNF Total

115
HDF Total


Causes distribution

98
OSF Total

95
PWF Total




Average failures per Type




TWF failure per tool wear

Tool wear level ● High ● Low ● Medium




PWF failure per Power



HDF failure per Temperature Difference

Temperature difference le... ● High ● Low



OSF failure per Strain

Strain level ● High ● Low

