500mV Pk-Pk Input Ripple Measured Output Error vs Switching Frequency

