



QUICK FIX MOTORS

Authorized Service Center
Noida - 201301

Estimate Number: **QFM/2025/12345**

Date: **23-05-2025**


Customer: **Priya Verma**

Vehicle: **Maruti Swift Dzire VXi**

Registration: **DL 08 AB 1234**

DAMAGE ASSESSMENT:

- Right front door: Heavily dented, needs replacement
- Right side bumper: Crushed, needs complete replacement
- Right panel: Creased, needs realignment and repainting
- Right mirror: Broken, needs replacement
- Headlight assembly: Damaged



SPARE PARTS REQUIRED:

	QTY	AMOUNT (Rs)
Right Front Door (Dzire) - OEM	1	28,000
Front Bumper (Dzire) - OEM	1	18,000
Side Panel (Dzire)	1	12,000
Right Side Mirror Assembly	1	4,500
Headlight Assembly - LED	1	16,000
Door lock mechanism	1	2,000

LABOUR:

	AMOUNT (Rs)
Door removal & fitting	8,000
Bumper removal & fitting	6,000
Panel repair & alignment	10,000
Painting (primer + topcoat)	12,000
Electrical alignment & testing	4,000
General maintenance & inspection	5,000

MISCELLANEOUS:

	AMOUNT (Rs)
Documentation & paperwork	2,000
Consumables (tape, thinner, etc.)	4,500

SUBTOTAL: Rs 1,61,000

GST (5%): Rs 8,050

TOTAL ESTIMATE: Rs 1,69,050

*Thank you for choosing Quick Fix Motors.
We assure you quality service and genuine parts.*

Terms & Conditions:

- This is an estimated cost and may vary after actual inspection and disassembly.
- All parts are OEM unless specified.
- Payment terms: 50% advance, balance on delivery.
- Estimate valid for 15 days from the date of issue.

Authorised Signatory
Quick Fix Motors