



FIRE DEPARTMENT REPORT

NOIDA FIRE BRIGADE

Incident Report Number:
NFB/2025/45612

Date of Incident : 18-05-2025
Time of Call : 02:35 AM
Location : 45-B, Palm Residency,
Sector 72, Noida

RESPONSE:

- First unit arrived : 02:52 AM (17 minutes)
- Fire controlled : 03:45 AM
- Fire extinguished : 04:00 AM

INCIDENT DETAILS:

Fire reported in residential flat. Upon arrival, fire was seen in living room area with flames extending to bedroom area. Fire was spreading rapidly.

CAUSE (Preliminary):

Electrical short circuit in wall socket area of living room.
Fire then spread due to presence of flammable materials (sofa, curtains).

SEVERITY: Medium (*confined to one flat, didn't spread to adjoining units*)

DAMAGE EXTENT:

Living room	90% destroyed
Bedroom	70% destroyed
Kitchen	10% smoke damage
Water damage (from firefighting)	Moderate

INJURIES: None reported

CASUALTIES: None

OBSERVATIONS:

1. Fire fighting was challenging due to presence of electrical hazards
2. Multiple extension cords in living room contributed to rapid spread
3. Lack of smoke detectors in property (violation of building code)
4. Fire spread pattern indicates single point of origin

RECOMMENDATION:

Further investigation by criminal branch recommended due to:

- Inconsistent fire spread pattern (skipped kitchen)
- Possible presence of accelerant (gasoline smell reported)
- Lack of occupants at time of fire
- High claim value

NO OBJECTION CERTIFICATE (NOC): ISSUED WITH CAUTION

(Issued pending criminal investigation conclusion)

Suresh Kumar
Fire Brigade Chief
Badge No.: NFB/456
Date: 18-05-2025



[IMPORTANT NOTE]:
THIS CASE IS FLAGGED FOR
INSURANCE FRAUD
INVESTIGATION