

Shift Production Incentive

Pacific Surfaces - Production: Silos > Mixer > Distributor/Kreos > Robo > Press > Oven > Jot

What this is

Every month each shift earns a **score**. The highest score earns the highest incentive, paid as a **percentage of your own salary** - everyone on the shift shares the same result, each person's amount based on their own pay.

Production is a team game. One person cannot win this alone, and one person cannot lose it alone. Silos, mixer, distributor, press, oven and Jot all count as one shift. You win together.

How the score is calculated

Your score is built from **two things only** - how much you made, and how good it was. The money is **split between them**, and both halves are counted **per shift, not per month**.

70% GOOD SLABS YOU MADE + 30% QUALITY OF WHAT YOU MADE

A big producer with poor quality loses the whole quality half; a careful shift that makes very little loses most of the larger half - **you need both**. And you are measured on your average per shift, not your total: 3 shifts making 300 good slabs (100 a shift) beats 10 shifts making 500 (50 a shift). Below 3 shifts in the month your rate is scaled down in proportion - one good night is not a month.

1. GOOD SLABS - 70% of the money

The slabs **your own MIS entry claims** - the starting and ending slab number you enter each hour. Those slabs are yours, and each counts by the grade QC finally gives it. An hour with no slab numbers entered claims nothing.

2. QUALITY - 30% of the money

The share of **your** slabs that came out Grade A. Quality follows the slab, not the clock: we look at what QC gave the slabs your MIS entry claimed, not whatever was polished during your hours - that is someone else's work.

QC grade	Counts as	Your grade share	Quality score
A (and A2)	1 good slab	87% or below	0%
B	half a slab	90%	30%
C (reject)	nothing	92%	50%
		95%	80%
		97% or above	100%

Your grade share is scored between an **87% minimum standard** and a **97% target** - you are paid for how far **above 87%** you get, and **97% scores the full 100%**. You do not have to be perfect to score perfectly. The plant already runs between 93% and 98%, so this is where places are won and lost: two points of grade share is worth twenty points of quality score.

A reject costs you nothing beyond itself - it is worth zero, never a minus. There is no reason to leave a slab out of MIS: hiding a bad one gains nothing and loses the good ones on the same line. A slab still waiting to be polished is **not** counted against you - your score rises when QC grades it.

How the pool is shared out

The pool is divided **in proportion to salary**: everyone is paid the same percentage of their own pay, so the shares always add up to exactly the pool.

Who	On the line	Monthly salary	Share of every pool
Operators	35	Rs 20,000 each	39%
Incharges	4	Rs 52,500 each	12%
Managers	5	Rs 1,75,000 each	49%
Total	44	Rs 17,85,000	100%

There are **44 people on the line** - 35 operators, 4 incharges and 5 managers - and a production salary bill of Rs 17.85 lakh a month. That bill is what turns a pool into a percentage. The pool itself is set by what the plant makes - the table overleaf. A Rs 7 lakh pool is 39% of one month's salary, and every person on the line takes 39% of their own.

What the month pays - count the slabs, read your own line

The pool everyone shares is set by the **good slabs the whole plant makes in the month**. It rises far faster than production does: 10,000 to 12,000 slabs is 20% more work and **double** the money. This is not last month's result - it is what is waiting to be earned.

Good slabs in the month	A shift averages	Total pool	Of one month's salary	Operator Rs 20,000	Incharge Rs 52,500	Manager Rs 1,75,000
6,000	67 a shift	Rs 2 lakh	11%	Rs 2,241	Rs 5,882	Rs 19,608
7,000	78 a shift	Rs 4 lakh	22%	Rs 4,482	Rs 11,765	Rs 39,216
8,000	89 a shift	Rs 7 lakh	39%	Rs 7,843	Rs 20,588	Rs 68,627
9,000	100 a shift	Rs 10 lakh	56%	Rs 11,204	Rs 29,412	Rs 98,039
10,000	111 a shift	Rs 15 lakh	84%	Rs 16,807	Rs 44,118	Rs 1,47,059
11,000	122 a shift	Rs 20 lakh	112%	Rs 22,409	Rs 58,824	Rs 1,96,078
12,000	133 a shift	Rs 30 lakh	168%	Rs 33,613	Rs 88,235	Rs 2,94,118

Your own figure is that same percentage of your own salary. "A shift averages" is the good slabs one shift needs to average across the 90 shifts in a month.

Read the second column, then the last three. About 11 more good slabs a shift moves the whole plant up one row - and every row up adds another 11% to 56% of a month's pay to every person on the line. 11,000 slabs is a full extra month's pay for everyone.

Every shift's output counts towards the same total, so **the whole plant has to get there together** - one shift alone cannot reach it, and one shift falling behind holds everyone back.

IMPORTANT - log in to your OWN shift only

The score is counted from the MIS entry. If you are logged in during another shift, your work is counted in THEIR score - not yours. This is the most common way a shift loses points it had already earned.

- **Log in at the start of your shift and LOG OUT at the end.** No login = no entry = no score for that hour. Stay logged in and the next shift's slabs are recorded under your name - and your own next shift may show nothing.
- **Enter every hour in MIS**, with the correct **shift number** (1 / 2 / 3), the **incharge names**, and the **starting and ending slab number** - that is what claims those slabs for your shift.
- **Never enter data for another shift.** If an hour was missed, tell your incharge - do not fill it in under the wrong shift.
- **Log the reason and minutes for any stoppage** - the electrical and mechanical incharges are scored on it.

We check this. The system compares the shift written on each record against the actual clock time. Records logged under the wrong shift are visible in the report and will be corrected - which may move points from one shift to another.

How the money is decided

At the end of the month each shift's **good slabs per shift** and **quality score** are worked out. The pool is split 70% on good slabs and 30% on quality, each shift takes its share of both, and that combined share becomes the **percentage of salary** paid to everyone on the shift. Good slabs are counted once QC has graded them, so a shift's score keeps rising as polishing catches up with it.

The pay table is what every shift earns when the three finish level. Win the month and your shift takes more; finish last and you take less. **But the row the plant lands on is worth far more than the place you finish in** - which is why the shift you beat this month is the same shift you need next month.

Conditions

- A shift below the **87% minimum quality standard** takes nothing from the quality half - the highest quantity alone does not win. At **97% and above the quality half scores in full**.
- **Safety comes first.** Any lost-time accident in the shift means no incentive that month, whatever the score.
- Scores are **published every month** and can be checked. If you believe a number is wrong, raise it with your incharge - every point traces back to the individual slab records behind it.

New on the board - OEE, the number world-class factories run on

Three numbers multiplied, all of them already coming from your own MIS entry - nothing new to write down. **They do not decide your money yet:** watch them for a month first.

Availability	Performance	Quality	OEE
Of the hours you logged, the time the line could run	Good slabs against 100 a running shift	Your QC grade share (A = 1, B = 0.5, C = 0)	The three multiplied together
over 95%	over 95%	over 98%	over 85%

Beside them is **MIS discipline**: hours filed out of eight, ranges typed too wide to be real, and slabs another shift claimed too. Each already costs you points under the rules above - now you can see it and fix the entry **while the month is still running**, instead of on payday.

Make more. Make it right. Log in to your own shift. Record everything.

Effective from: _____ Signed: _____ Date: _____

Questions: speak to your Production Incharge.