FlightGear – Robinson R22 Checklist

(not all functions below are implemented yet)

Seat Belts
 Fuel shut-off valve
 Cyclic/collective friction

Fastened
On
Off

Cyclic/collective, pedals
 Throttle
 Collective
 Full travel free
 Full travel free
 Full down, friction on

Cyclic neutral
 Pedals
 Friction on Neutral

• Governor Off (if equipped)

Circuit breakers
Carb heat
Mixture
Mixture guard
All switches/avionics
In
Full rich
Installed
Off

• Clutch Disengaged

Altimeter Set

• Rotor brake Disengaged

• Map light Off

START-UP

Master switch

On

Throttle twists (priming)
 Throttle
 Area
 Strobe light
 As required Closed
 Clear
 On

• Ignition switch Start, then both

Started-On light
Set idle speed
Clutch switch
Alternator switch

Out

55%

Engaged

On

• Oil pressure in 30 sec. 25 psi min.

Avionics/nav lights
Clutch light
Warm-up RPM
Engine gauges
Warning lights
On
70-75 %
Green
Out

Mag drop @ 75% RPM
 Carb heat check
 Sprag clutch check from 75% rpm
 Mag drop @ 75% RPM
 CAT rise/drop
 Needles split

Doors Closed and latched
 Limit MAP chart Check
 Cyclic/collective friction Off

• Governor on RPM 102 – 104 %

• Lift collective /reduce RPM Warning horn/light at 97 % RPM

(Note: This chart is for simulation purposes only)