PMP-104: Inspection Record

Fictional inspection record 01 for pump PMP-104. The recorded pressure was 8.2 bar. The mechanical seal had no visible leakage at the time of inspection.

The operator recorded elevated vibration. No cause was established. The record contains no motor power measurement and does not certify the equipment as safe.

This page is an image-only scan created for testing OCR. Its contents were authored for the ConceptGraph demonstration, not collected from real equipment.

Interpreting the Record

To interpret inspection record 01 for PMP-104, compare its measured pressure with the operating range in equipment-specification.pdf. Compare its seal observation with the inspection requirements in equipment-maintenance.pdf.

The specification, guide, and inspection record describe different facts. An observation does not override a specification, and a maintenance interval is not an inspection result. Use the cited pages rather than treating these documents as interchangeable.