

# Inspection Report V-1202 — Shell Thickness Survey January 2030

## 1. Equipment Details

Equipment: V-1202 Reflux Accumulator. Design pressure 12.5 barg. Design temperature 150 degC. Material SA-516 Gr.70. Nominal shell thickness 12.0 mm. Minimum allowable thickness 7.50 mm. Previous inspection 2028-11-20.

## 2. Thickness Survey

Ultrasonic measurements were taken at six condition monitoring locations on 2030-01-22 using a calibrated DM5E gauge. Surface temperature 31 degC. All readings are the minimum of five shots at each location.

| CML    | Location         | 2028 (mm) | 2030 (mm) | t-min (mm) |
|--------|------------------|-----------|-----------|------------|
| CML-01 | Top head         | 11.90     | 11.75     | 7.50       |
| CML-02 | Shell course 1   | 11.85     | 11.40     | 7.50       |
| CML-03 | Shell course 2   | 11.70     | 10.95     | 7.50       |
| CML-04 | Bottom shell     | 11.40     | 9.85      | 7.50       |
| CML-05 | Outlet nozzle N2 | 11.20     | 9.10      | 7.50       |
| CML-06 | Boot             | 10.80     | 8.35      | 7.50       |

## 3. Findings

Wall loss is concentrated in the boot and the outlet nozzle, which is consistent with water-phase corrosion at the liquid interface. CML-06 has lost 2.45 mm since 2028 and is the governing location. No through-wall defect was detected. External coating is intact.

## 4. Recommendation

Re-inspect CML-06 and CML-05 at twelve-month intervals rather than the standard thirty-six. Boot drainage should be reviewed during the 2031 turnaround. Next full survey due 2031-01.

## 5. Sign-off

Inspected by: S. Nair, Senior Inspection Engineer. Reviewed by: M. Devadiga, Maintenance Head. Date: 2030-01-24.