IOT ASSIGNMENT 2

PYTHON CODE

Build Python code, Generate Temperature and Humidity values (Use Random function to generate values) and write a condition to detect an alarm in case of high temperature and high Humidity.

OUTPUT:

```
Shell

Temperature is : 23.329320952266947 C

Humidity is : 32.35526265699562 %

> |
```