		EVENT ANA	ALYSIS REPORT	<u> </u>	·	
UNIT NO: 02	TPS: Khaperkhe					
1. *HO Code :	Station Code : T003	Time - 12:14 Hrs	Date - 20/11/201	No. of day	ys from last sync. : 37 days	
2. Operating con	ditions at the time of					
Load		Coal Cycles in service			Oil Support	
20 MW			В		AB elev. 2 Nos.	
3. Nature of Even	t: T.A. Set withdraw	n due to "Critical Co	al Stock".		·	
4. Name of First	Up , Main Protections	& Protection on whi	ch GCB tripped :	10		
Turbine Trip t	to Boiler Trip (First U	p), Generator Protec	ction Operated, Clas	s B lock out relay o	perated, Generator	
	pped, GCB opened on					
	s: On dt. 20-11-17 at		n 20 MW load with	C/c B I/S and oil su	pport at AB elevation	
T.G set Hand t	ripped due to poor co	al receipt.				
5 B) Remedial Ac	ction/work done: Rou	tine S/D maintenan	ce work carried out			
			t .	¥		
Root Cause Ana	lysis: Due to poor coa	al receipt set hand tr	ripped (withdrawn)			
7. Preventive act	ion suggested (Short T	Term):			9	
	,					
8. Preventive act	ion suggested (Long T	erm):				
					Fime: 06:53 hrs Date: 25/09/2013	
9. Similar event occurred last time:-		Unit	Unit No #2, 210 MW		Date: 25/09/2017	
Event: T.A. Set	withdrawn due to "Cr	ritical Coal Stock".				
	s: Routine S/D mainte		l out.			
	ion Status of Long Ter					
10. Boiler lighted up					9/11/2017	
11. T-A Set Synchronized		Time -	19:00 Hrs	00 Hrs Date - 29/11		
12. Remark :					0	
					w	
					Chief Engineer	
					Chief Engineer	
3. Recommenda	tions of Works Section	n:			Chief Engineer	
	ntions of Works Section ment/Replacement				Chief Engineer	
1. Procure					Chief Engineer	
1. Procurer	ment/Replacement				Chief Engineer	
1. Procurer 2. Operation 3. Delay in	ment/Replacement	Plan:			Chief Engineer	
1. Procurer 2. Operation 3. Delay in	ment/Replacement in the control of t	Plan:			Chief Engineer	
1. Procured 2. Operation 3. Delay in 4. Delay in 5. Training	ment/Replacement in the control of t	Plan: nit:	tory & point is clos	sed:	Chief Engineer	